



# Waterboro

Map Lot 042-00A-146

Account 2539

Location 18 LYNWOOD DRIVE


Card 1 Of 1 9/23/2024

Building Style	<b>2 Ranch</b>		
1.Conv	5.Garr/Col	9.Other	
2.Ranch	6.Split	10.Mohome	
3.R Ranch	7.Contemp/	11.Condo	
4.Cape	8.Log	12.	
Dwelling Units	<b>1</b>		
Other Units	<b>0</b>		
Stories	<b>1 One Story</b>		
1.1	4.1.50	7.1.25	
2.2	5.1.75	8.	
3.3	6.2.50	9.	
Exterior Walls	<b>1 Wood Siding</b>		
0.Wood	4.Asb/Asph	8.Alum/Vin	
1.Wood	5.T-111	9.Other	
2.Wd Sh	6.Br/St	11.	
3.Compos.	7.Nov	12.	
Roof Surface	<b>1 Asphalt Shingles</b>		
1.Asphalt	4.Composit	7.	
2.Slate	5.Wood	8.	
3.Metal	6.Other	9.	
SF Masonry Trim	<b>0</b>		
OPEN-3-	<b>0</b>		
OPEN-4-	<b>0</b>		
Year Built	<b>1989</b>		
Year Remodeled	<b>0</b>		
Foundation	<b>1 Concrete</b>		
1.Concrete	4.Wood	7.	
2.C Block	5.Slab	8.	
3.Br/Stone	6.Prs/Post	9.	
Basement	<b>4 Full Basement</b>		
1.1/4 Bmt	4.Full Bmt	7.	
2.1/2 Bmt	5.None	8.	
3.3/4 Bmt	6.	9.None	
Bsmt Gar # Cars	<b>1</b>		
Wet Basement	<b>1 Dry Basement</b>		
1.Dry	4.	7.	
2.Damp	5.	8.	
3.Wet	6.	9.	

SF Bsmt Living	<b>800</b>		
Fin Bsmt Grade	<b>3 100</b>		
OPEN 5 OPTIONAL	<b>0</b>		
Heat Type	<b>100%</b>	<b>1 Hot Water BB</b>	
1.HWBB	5.FWA	9.No Heat	
2.HWCI	6.GravWA	10.	
3.HWRAD	7.Electric	11.	
4.Steam	8.F/WallM	12.	
Cool Type	<b>0%</b>	<b>9 None</b>	
1.Refrig	4.W&C Air	7.	
2.Evapor	5.	8.	
3.H Pump	6.	9.None	
Kitchen Style	<b>2 Typical</b>		
1.Modern	4.Obsolete	7.	
2.Typical	5.	8.	
3.Old Type	6.	9.None	
Bath(s) Style	<b>2 Typical Bath(s)</b>		
1.Modern	4.Obsolete	7.	
2.Typical	5.	8.	
3.Old Type	6.	9.None	
# Rooms	<b>0</b>		
# Bedrooms	<b>3</b>		
# Full Baths	<b>1</b>		
# Half Baths	<b>0</b>		
# Addn Fixtures	<b>0</b>		
# Fireplaces	<b>0</b>		



Layout	<b>1 Typical</b>		
1.Typical	4.	7.	
2.Inadeq	5.	8.	
3.Not func	6.	9.	
Attic	<b>9 None</b>		
1.1/4 Fin	4.Full Fin	7.1/4 Unfi	
2.1/2 Fin	5.F/Stair	8.	
3.3/4 Fin	6.1/2 Unfi	9.None	
Insulation	<b>1 Full</b>		
1.Full	4.Minimal	7.	
2.Heavy	5.Unk	8.	
3.Capped	6.	9.None	
Unfinished %	<b>0%</b>		
Grade & Factor	<b>3 Average 105%</b>		
1.E Grade	4.B Grade	7.AAA Grad	
2.D Grade	5.A Grade	8.	
3.C Grade	6.AA Grade	9.Same	
SQFT (Footprint)	<b>960</b>		
Condition	<b>5 Above Average</b>		
1.Poor	4.Avg	7.V G	
2.Fair	5.Avg+	8.Exc	
3.Avg-	6.Good	9.Same	
Phys. % Good	<b>0%</b>		
Funct. % Good	<b>100%</b>		
Functional Code	<b>9 None</b>		
1.Incomp	4.Small	7.Layout	
2.O-Built	5.CDU	8.Other	
3.Damage	6.Style	9.None	
Econ. % Good	<b>100%</b>		
Economic Code	<b>None</b>		
0.None	3.Services	7.	
1.Location	4.Traffic	8.	
2.Encroach	9.None	9.	
Entrance Code	<b>0</b>		
1.Interior	4.Vacant	7.	
2.Refusal	5.Estimate	8.	
3.Informed	6.Office	9.RS	
Information Code	<b>0</b>		
1.Owner	4.Agent	7.	
2.Relative	5.Estimate	8.	
3.Tenant	6.Other	9.SNY	



Date Inspected

### Additions, Outbuildings & Improvements

Type	Year	Units	Grade	Cond	Phys.	Funct.	Sound Value	
68 Wood Deck	2023	372	4 100	6	0 %	100 %		1.One Story Fram
24 Frame Shed	0	120	0 0	0	0 %	0 %		2.Two Story Fram
					%	%		3.Three Story Fr
					%	%		4.1 & 1/2 Story
					%	%		5.1 & 3/4 Story
					%	%		6.2 & 1/2 Story
					%	%		21.Open Frame Por
					%	%		22.Encl Frame Por
					%	%		23.Frame Garage
					%	%		24.Frame Shed
					%	%		25.Frame Bay Wind
					%	%		26.1SFr Overhang
					%	%		27.Unfin Basement
					%	%		28.Unfinished Att
					%	%		29.Finished Attic