




BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	0	<b>INSULATION</b>			
1. Conv. 6. Split Lev.	2	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1		
2. Ranch 7. Contemp.				2. Heavy 9. None			
3. R. Ranch 8. Log		<b>HEAT TYPE</b>	5			3. Capped	
4. Cape 9. Other		1. HW BB 6. Grav. WA				<b>UNFINISHED %</b>	%
5. Garrison		2. HW CI 7. Electric				<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>	3. HW Radiant 8. Units			1. E 4. B	3		
<b>OTHER UNITS</b>	4. Steam 9. No Heat			2. D 5. A			
<b>STORIES</b>	5. FWA	%	3. C 6. AA				
1. One 4. 1 1/2	1	<b>COOL TYPE</b>		<b>SQ. FOOTAGE</b>	1716		
2. Two 5. 1 3/4		1. Central 9. None	9	<b>CONDITION</b>	4		
3. Three 6. 2 1/2			%	1. Poor 5. Avg +			
<b>EXTERIOR WALLS</b>	1	<b>KITCHEN STYLE</b>	2	2. Fair 6. Good		%	
1. Clapboard 6. BR/Stone		1. Good 3. Old Style			3. Avg - 7. V Good		
2. WD.SH. 7. Novelty		2. Typical 4. Obsolete			4. Avg. 8. Exc.		
3. Comp. 8. AL/Vinyl		<b>BATH(S) STYLE</b>		2	<b>PHYS. % GOOD</b>		%
4. ASB/ASP 9. Other		1. Good 3. Old Style					<b>FUNCT. % GOOD</b>
5. T1-11	2. Typical 4. Obsolete		<b>FUNCT. CODE</b>				
<b>ROOF SURFACE</b>	3	<b># ROOMS</b>	5		1. Incomp. 5. CDU	%	
1. Asphalt 4. Comp.		<b># BEDROOMS</b>	2		2. Overbuilt 6. Style		
2. Slate 5. Wood		<b>#FULL BATHS</b>	7	3. Delap. 7. Layout			
3. Metal 6. Other	1978	<b># HALF BATHS</b>	1	4. Small Size 8. Other	%		
<b>S/F MASONRY TRIM</b>		<b># ADDN FIXTURES</b>		9. None			
<b>YEAR BUILT</b>		<b># FIREPLACES</b>	=	<b>ECON. % GOOD</b>		%	
<b>YEAR REMODELED</b>		<b># HEARTHES</b>		<b>ECON. CODE</b>			
<b>FOUNDATION</b>		1	<b>LAYOUT</b>	1		1. Location 3. Services	%
1. Conc. 4. Wood	1. Typical 2. In adeq.			2. Encroach 9. None			
2. C Blk 5. Slab	<b>ATTIC</b>		7	<b>ENTRANCE CODE</b>			
3. Br./Stone 6. Piers	1. 1/4 Fin 4. Full Fin.			1. Inspect. 3. Vacant	1		
<b>BASEMENT</b>	2. 1/2 Fin. 5. Fl/Stairs			2. Refused 5. Estim.			
1. 1/4 3. 3/4 5. Crawl	4	3. 3/4 Fin. 9. None		3. Info Only			
2. 1/2 4. Full 6. None		<b>INT COMP TO EXIT + = -</b>		<b>INFO. CODE</b>			
<b>BSMT GAR # CARS</b>		0	<b>INSPECTED BY</b>	JLO	1. Owner 4. Agent	1	
<b>WET BASEMENT</b>	1	<b>DATE INSPECTED</b>	10/12/05	2. Relative 5. Estimate			
1. Dry 3. Wet				3. Tenant 6. Other			
2. Damp 9. None				2. Refused 5. Estim.			



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWL	001	1978	1716	3.00	4	---	---	1. 1S Fr.
DK	068		50	---	---	---	---	2. 2S Fr.
GAR	023	1990	480	3.00	4	---	---	3. 3S Fr.
						---	---	4. 1 1/2S Fr.
						---	---	5. 1 3/4S Fr.
						---	---	6. 2 1/2S Fr.
						---	---	Add 10 for Bsmt
						---	---	21. OFP
						---	---	22. EFP
						---	---	23. Garage
						---	---	24. Shed
						---	---	25. Bay Window
						---	---	26. Overhang
						---	---	27. Unf. Bsmt
						---	---	28. Unf. Attic
						---	---	29. Fin. Attic
						---	---	Add 20 for 2 Story
						---	---	61. Carport
						---	---	62. Patio
						---	---	63. Swimming Pool
						---	---	64. Tennis Court
						---	---	65. Stable w/loft
						---	---	66. Greenhouse
						---	---	67. Natatorium
						---	---	68. Wood Deck
						---	---	69. Jacuzzi

PHOTO

NOTES: