




BUILDING RECORD

MAP LOT ACCOUNT NO. 209 ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	0	<b>INSULATION</b>		
1. Conv. 6. Split Lev.	1	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>		%
5. Garrison				<b>GRADE &amp; FACTOR</b>		
<b>DWELLING UNITS</b>	1	<b>HEAT TYPE</b>	10% masonry	1. E 4. B	3	
<b>OTHER UNITS</b>		1. HW BB 6. Grav. WA		2. D 5. A		
<b>STORIES</b>		2. HW Cl 7. Electric		3. C 6. AA		
1. One 4. 1 1/2	2	3. HW Radiant 8. Units	4	<b>SQ. FOOTAGE</b>		720
2. Two 5. 1 3/4			4. Steam 9. No Heat			<b>CONDITION</b>
3. Three 6. 2 1/2			5. FWA	90%	1. Poor 5. Avg +	4
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>		2. Fair 6. Good		
1. Clapboard 6. BR./Stone	1	1. Central 9. None	9%	3. Avg - 7. V Good		
2. WD.SH. 7. Novelty			<b>KITCHEN STYLE</b>		4. Avg. 8. Exc.	
3. Comp. 8. AL/Minyl			1. Good 3. Old Style		<b>PHYS. % GOOD</b>	%
4. ASB/ASP 9. Other			2. Typical 4. Obsolete		<b>FUNCT. % GOOD</b>	%
5. T1-11			<b>BATH(S) STYLE</b>		<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		<b># ROOMS</b>		1. Incomp. 5. CDU	9	
1. Asphalt 4. Comp.	1	<b># BEDROOMS</b>	4	2. Overbuilt 6. Style		
2. Slate 5. Wood		<b># FULL BATHS</b>	2	3. Delap. 7. Layout		
3. Metal 6. Other		<b># HALF BATHS</b>		4. Small Size 8. Other		
<b>S/F MASONRY TRIM</b>		<b># ADDN FIXTURES</b>		9. None		
<b>YEAR BUILT</b>	1868	<b># FIREPLACES</b>		<b>ECON. % GOOD</b>	%	
<b>YEAR REMODELED</b>		<b># HEARTHES</b>		<b>ECON. CODE</b>		
<b>FOUNDATION</b>		<b>LAYOUT</b>		1. Location 3. Services	9	
1. Conc. 4. Wood	3	1. Typical 2. In adeg.	1	2. Encroach 9. None		
2. C Blk 5. Steb		<b>ATTIC</b>		<b>ENTRANCE CODE</b>		
3. Br./Stone 6. Piers			1. 1/4 Fin 4. Full Fin.	5	1. Inspt. 3. Vacant	
<b>BASEMENT</b>		2. 1/2 Fin. 5. Fl/Stairs		2. Refused 5. Estim.	5	
1. 1/4 3. 3/4 5. Crawl	4	3. 3/4 Fin. 9. None	UNFIN	3. Info Only		
2. 1/2 4. Full 6. None		<b>INT COMP TO EXIT + = -</b>		<b>INFO. CODE</b>		
<b>BSMT GAR # CARS</b>		<b>INSPECTED BY</b>	JLD	1. Owner 4. Agent	5	
<b>WET BASEMENT</b>	2	<b>DATE INSPECTED</b>	11/16/05	2. Relative 5. Estimate		
1. Dry 3. Wet						3. Tenant 6. Other
2. Damp 9. None				2. Refused 5. Estim.		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
DWC	02		720	3.00	4	%	%	1. 1S Fr.
ADD	04		408		1	%	%	2. 2S Fr.
ADD	01		216		2	%	%	3. 3S Fr.
ADD	01		561		3	%	%	4. 1 1/2S Fr.
BARN	65		2400			50%	100%	5. 1 3/4S Fr.
BARN	65		1000			50%	100%	6. 2 1/2S Fr.
MA SHD	34		288			%	%	Add 10 for Bsmt
SHD	23		620			%	%	21. OFP
BARN	65		929			%	%	22. EFP
SHD	23		276			%	%	23. Garage
ATTC	38		561			%	%	24. Shed

PHOTO

NOTES:

- 25. Bay Window
- 26. Overhang
- 27. Unf. Bsmt
- 28. Unf. Attic
- 29. Fin. Attic
- Add 20 for 2 Story
- 61. Carport
- 62. Patio
- 63. Swimming Pool
- 64. Tennis Court
- 65. Stable w/loft
- 66. Greenhouse
- 67. Natatorium
- 68. Wood Deck
- 69. Jacuzzi