


BUILDING RECORD

MAP LOT ACCOUNT NO. 367 ADDRESS CARD NO. OF

| | | | | | | |
|-------------------------------|---------|-------------------------------|----------|------------------------------|----------------------|---|
| BUILDING STYLE | | S/F BSMT LIVING | - | INSULATION | | |
| 1. Conv. 6. Split Lev. | 2 MH | FIN BSMT GRADE | | 1. Full 4. Minimal | 1 | |
| 2. Ranch 7. Contemp. | | | | 2. Heavy 9. None | | |
| 3. R. Ranch 8. Log | | | | 3. Capped | | |
| 4. Cape 9. Other | | | | UNFINISHED % | | % |
| 5. Garrison | | | | GRADE & FACTOR | | |
| DWELLING UNITS | 1 | | 5 | 1. E 4. B | 2 | |
| OTHER UNITS | | | | 2. D 5. A | | |
| STORIES | 1 | | | 3. C 6. AA | | |
| 1. One 4. 1 1/2 | | | | SQ. FOOTAGE (980) 924 | | |
| 2. Two 5. 1 3/4 | | | | CONDITION | 4 | |
| 3. Three 6. 2 1/2 | | | 9 % | 1. Poor 5. Avg + | | |
| EXTERIOR WALLS | | | | 2. Fair 6. Good | | |
| 1. Clapboard 6. BR./Stone | 8 | KITCHEN STYLE | 2 | 3. Avg - 7. V Good | | |
| 2. WD.SH. 7. Novelty | | | | 4. Avg. 8. Exc. | % | |
| 3. Comp. 8. AL/Vnly | | | | BATH(S) STYLE | PHYS. % GOOD | % |
| 4. ASB/ASP 9. Other | | | | 1. Good 3. Old Style | FUNCT. % GOOD | % |
| 5. T1-11 | | | | 2. Typical 4. Obsolete | FUNCT. CODE | |
| ROOF SURFACE | 3 | # ROOMS | 2 | 1. Incomp. 5. CDU | 53 | |
| 1. Asphalt 4. Comp. | | # BEDROOMS | 2 | 2. Overbuilt 6. Style | | |
| 2. Slate 5. Wood | | # FULL BATHS | 1 | 3. Delap. 7. Layout | | |
| 3. Metal 6. Other | | # HALF BATHS | | 4. Small Size 8. Other | | |
| S/F MASONRY FRM | | # ADDN FIXTURES | | 9. None | | |
| YEAR BUILT (2008) 1986 | | # FIREPLACES | 0 | ECON. % GOOD | % | |
| YEAR REMODELED | | # HEARTHES | | ECON. CODE | | |
| FOUNDATION | | LAYOUT | 1 | 1. Location 3. Services | 53 | |
| 1. Conc. 4. Wood | 5 | 1. Typical 2. In adeq. | | 2. Encroach 9. None | | |
| 2. C Blk 5. Slab | | ATTIC | | ENTRANCE CODE | | |
| 3. Br./Stone 6. Piers | | | | 1. Inspct. 3. Vacant | | |
| BASEMENT | 6 | 1. 1/4 Fin. 4. Full Fin. | 9 | 2. Refused 5. Estim. | | |
| 1. 1/4 3. 3/4 5. Crawl | | 2. 1/2 Fin. 5. FV/Stairs | | 3. Info Only | | |
| 2. 1/2 4. Full 6. None | | 3. 3/4 Fin. 9. None | | INFO. CODE | 56 CORNS | |
| BSMT GAR # CARS | 0 | INT COMP TO EXIT + = - | | 1. Owner 4. Agent | | |
| WET BASEMENT | 9 | INSPECTED BY | JAG | 2. Relative 5. Estimate | | |
| 1. Dry 3. Wet | | DATE INSPECTED | 11/29/05 | 3. Tenant 6. Other | | |
| 2. Damp 9. None | | | | 2. Refused 5. Estim. | | |



| ADDITIONS, OUTBUILDINGS & IMPROVEMENTS | | | | | | PERCENT GOOD | | CODES |
|--|-------|-------|-------|------|-------|--------------|--------------------|-------|
| TYPE | YEAR | UNITS | GRADE | COND | Phys. | Funct. | | |
| DWL | 1986 | 924 | 3.00 | 4 | % | % | 1. 1S Fr. | |
| JHD | 24 | 64 | | 3 | % | % | 2. 2S Fr. | |
| MOHS | 2008 | 980 | 3.1 | 2 | % | % | 3. 3S Fr. | |
| SLAB | 14x70 | 980 | 3.2 | 7 | % | % | 4. 1 1/2S Fr. | |
| | | | | | | | 5. 1 3/4S Fr. | |
| | | | | | | | 6. 2 1/2S Fr. | |
| | | | | | | | Add 10 for Bsmt | |
| | | | | | | | 21. OFP | |
| | | | | | | | 22. EFP | |
| | | | | | | | 23. Garage | |
| | | | | | | | 24. Shed | |
| | | | | | | | 25. Bay Window | |
| | | | | | | | 26. Overhang | |
| | | | | | | | 27. Unf. Bsmt | |
| | | | | | | | 28. Unf. Attic | |
| | | | | | | | 29. Fin. Attic | |
| | | | | | | | Add 20 for 2 Story | |
| | | | | | | | 61. Carport | |
| | | | | | | | 62. Patio | |
| | | | | | | | 63. Swimming Pool | |
| | | | | | | | 64. Tennis Court | |
| | | | | | | | 65. Stable w/loft | |
| | | | | | | | 66. Greenhouse | |
| | | | | | | | 67. Natatorium | |
| | | | | | | | 68. Wood Deck | |
| | | | | | | | 69. Jacuzzi | |

PHOTO

NOTES: MOHS 14x70 2010 FR 2011