




BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>	
1. Conv.	8. Split Lev.	<b>FIN BSMT GRADE</b>		1. Full	4. Minimal
2. Ranch	7. Contemp.			2. Heavy	9. None
3. R. Ranch	8. Log			3. Capped	
4. Cape	9. Other			<b>UNFINISHED %</b>	
5. Garrison				<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>		1. E	4. B
<b>OTHER UNITS</b>		1. HW BB	6. Grav. WA	2. D	5. A
<b>STORIES</b>		2. HW CI	7. Electric	3. C	6. AA
1. One	4. 1 1/2	3. HW Radiant	8. Units	<b>SQ. FOOTAGE</b>	
2. Two	5. 1 3/4	4. Steam	9. No Heat	<b>CONDITION</b>	
3. Three	6. 2 1/2	5. FWA		1. Poor	5. Avg +
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>		2. Fair	6. Good
1. Clapboard	6. BR./Stone	1. Central	9. None	3. Avg -	7. V Good
2. WD.SH.	7. Novelty			4. Avg	8. Exc.
3. Comp.	8. AL/Vinyl			<b>PHYS. % GOOD</b>	
4. ASB/ASP	9. Other	<b>KITCHEN STYLE</b>		<b>FUNCT. % GOOD</b>	
5. T1-11		1. Good	3. Old Style	<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		2. Typical	4. Obsolete	1. Incomp.	5. CDU
1. Asphalt	4. Comp.	<b>BATH(S) STYLE</b>		2. Overbuilt	6. Style
2. Slate	5. Wood	1. Good	3. Old Style	3. Delap.	7. Layout
3. Metal	6. Other	2. Typical	4. Obsolete	4. Small Size	8. Other
<b>S/F MASONRY TRIM</b>		<b># ROOMS</b>		9. None	
<b>YEAR BUILT</b>		<b># BEDROOMS</b>		<b>ECON. % GOOD</b>	
<b>YEAR REMODELED</b>		<b># FULL BATHS</b>		<b>ECON. CODE</b>	
<b>FOUNDATION</b>		<b># HALF BATHS</b>		1. Location	3. Services
1. Conc.	4. Wood	<b># ADDN FIXTURES</b>		2. Encroach	9. None
2. C Blk	5. Slab	<b># FIREPLACES</b>		<b>ENTRANCE CODE</b>	
3. Br./Stone	6. Piers	<b># HEARTHES</b>		1. Inspct.	3. Vacant
<b>BASEMENT</b>		<b>LAYOUT</b>		2. Refused	5. Estim.
1. 1/4	3. 3/4	1. Typical	2. In adeq.	<b>INFO. CODE</b>	
2. 1/2	4. Full	<b>ATTIC</b>		3. Info Only	
5. Crawl	6. None	1. 1/4 Fin.	4. Full Fin.	<b>ADDITIONS, OUTBUILDINGS &amp; IMPROVEMENTS</b>	
<b>BSMT GAR # CARS</b>		2. 1/2 Fin.	5. Fl/Stairs	TYPE	
<b>WET BASEMENT</b>		3. 3/4 Fin.	9. None	YEAR	
1. Dry	3. Wet	<b>INT COMP TO EXIT + = -</b>		UNITS	
2. Damp	9. None	<b>INSPECTED BY</b>		GRADE	
		1. Owner		COND	
		2. Relative		PERCENT GOOD	
		3. Tenant		Phys.	Funct.
		2. Refused		1. 1S Fr.	
		5. Estim.		2. 2S Fr.	
				3. 3S Fr.	
				4. 1 1/2S Fr.	
				5. 1 3/4S Fr.	
				6. 2 1/2S Fr.	
				Add 10 for Bsmt	
				21. OFF	
				22. EFP	
				23. Garage	
				24. Shed	
				25. Bay Window	
				26. Overhang	
				27. Unf. Bsmt	
				28. Unf. Attic	
				29. Fin. Attic	
				Add 20 for 2 Story	
				61. Carport	
				62. Patio	
				63. Swimming Pool	
				64. Tennis Court	
				65. Stable w/loft	
				66. Greenhouse	
				67. Natatorium	
				68. Wood Deck	
				69. Jacuzzi	



PHOTO

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
MH	998	1989	14x20	3.-	4	---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	
						---	---	

NOTES: