


MAP **8** LOT **13A** ACCOUNT NO. **895** BUILDING RECORD ADDRESS **19 Hickory Ln** CARD NO. OF

| | | | | | | |
|---------------------------|-------------|-------------------------------|-----------------|---------------------------|-------------|--|
| BUILDING STYLE | | S/F BSMT LIVING | | INSULATION | | |
| 1. Conv. 6. Split Lev. | 2 | FIN BSMT GRADE | | 1. Full 4. Minimal | 1 | |
| 2. Ranch 7. Contemp. | | | | 2. Heavy 9. None | | |
| 3. R. Ranch 8. Log | | | | 3. Capped | | |
| 4. Cape 9. Other | | | | UNFINISHED % | | |
| 5. Garrison | | | | GRADE & FACTOR | | |
| DWELLING UNITS | | | 1 | 1. E 4. B | 3 | |
| OTHER UNITS | | | | 2. D 5. A | | |
| | | | | 3. C 6. AA | | |
| STORIES | | | | SQ. FOOTAGE | 1134 | |
| 1. One 4. 1 1/2 | 1 | COOL TYPE | | CONDITION | 4 | |
| 2. Two 5. 1 3/4 | | | | 1. Poor 5. Avg + | | |
| 3. Three 6. 2 1/2 | | | | 2. Fair 6. Good | | |
| EXTERIOR WALLS | | | 9 | 3. Avg - 7. V Good | | |
| 1. Clapboard 6. BR./Stone | 1 | KITCHEN STYLE | | 4. Avg. 8. Exc. | | |
| 2. WD.SH. 7. Novelty | | | | PHYS. % GOOD | | |
| 3. Comp. 8. AL/Vinyl | | | | FUNCT. % GOOD | | |
| 4. ASB/ASP 9. Other | | | 2 | FUNCT. CODE | | |
| 5. T1-11 | | | | 1. Incomp. 5. CDU | 9 | |
| ROOF SURFACE | | | | 2. Overbuilt 6. Style | | |
| 1. Asphalt 4. Comp. | 1 | # ROOMS | 2 | 3. Delap. 7. Layout | | |
| 2. Slate 5. Wood | | | | 4. Small Size 8. Other | | |
| 3. Metal 6. Other | | | | 9. None | | |
| S/F MASONRY TRIM | | | | ECON. % GOOD | | |
| YEAR BUILT | 1973 | # FIREPLACES | | ECON. CODE | 9 | |
| YEAR REMODELED | | # HEARTHES | | 1. Location 3. Services | | |
| FOUNDATION | | LAYOUT | | 2. Encroach 9. None | | |
| 1. Conc. 4. Wood | 5 | 1. Typical 2. In adeg. | 1 | ENTRANCE CODE | 5 | |
| 2. C Blk 5. Stab | | | | 1. Inspct. 3. Vacant | | |
| 3. Br./Stone 6. Piers | | | | 2. Refused 5. Estim. | | |
| BASEMENT | | ATTIC | | 3. Info Only | | |
| 1. 1/4 3. 3/4 5. Crawl | 9 | 1. 1/4 Fin 4. Full Fin. | 9 | INFO. CODE | 5 | |
| 2. 1/2 4. Full 6. None | | | | 1. Owner 4. Agent | | |
| | | | | 2. Relative 5. Estimate | | |
| BSMT GAR # CARS | | INT COMP TO EXIT + = - | | 3. Tenant 6. Other | | |
| WET BASEMENT | | INSPECTED BY | TMC | 4. Refused 5. Estim. | | |
| 1. Dry 3. Wet | 9 | DATE INSPECTED | 10.27.05 | | | |
| 2. Damp 9. None | | | | | | |



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

| | TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD | | CODES |
|-----|------|------|-------|-------|------|--------------|--------|--------------------|
| | | | | | | Phys. | Funct. | |
| Add | 001 | | 504 | 3 | 4 | % | % | 1. 1S Fr. |
| OPR | 021 | | 78 | 3 | 4 | % | % | 2. 2S Fr. |
| | | | | | | % | % | 3. 3S Fr. |
| | | | | | | % | % | 4. 1 1/2S Fr. |
| | | | | | | % | % | 5. 1 3/4S Fr. |
| | | | | | | % | % | 6. 2 1/2S Fr. |
| | | | | | | % | % | Add 10 for Bsmt |
| | | | | | | % | % | 21. OFP |
| | | | | | | % | % | 22. EFP |
| | | | | | | % | % | 23. Garage |
| | | | | | | % | % | 24. Shed |
| | | | | | | % | % | 25. Bay Window |
| | | | | | | % | % | 26. Overhang |
| | | | | | | % | % | 27. Unf. Bsmt |
| | | | | | | % | % | 28. Unf. Attic |
| | | | | | | % | % | 29. Fin. Attic |
| | | | | | | % | % | Add 20 for 2 Story |
| | | | | | | % | % | 61. Carport |
| | | | | | | % | % | 62. Patio |
| | | | | | | % | % | 63. Swimming Pool |
| | | | | | | % | % | 64. Tennis Court |
| | | | | | | % | % | 65. Stable w/loft |
| | | | | | | % | % | 66. Greenhouse |
| | | | | | | % | % | 67. Natatorium |
| | | | | | | % | % | 68. Wood Deck |
| | | | | | | % | % | 69. Jacuzzi |

PHOTO

10.27.05 037

NOTES: