


230

BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

BUILDING STYLE		4	S/F BSMT LIVING		100 %	INSULATION		1
1. Conv.	6. Split Lev.		FIN BSMT GRADE			1. Full	4. Minimal	
2. Ranch	7. Contemp.	1	HEAT TYPE		9 %	2. Heavy	9. None	3+
3. R. Ranch	8. Log		1. HW BB 6. Grav. WA			3. Capped		
4. Cape	9. Other	4	COOL TYPE		9 %	UNFINISHED %		5
5. Garrison			1. Central 9. None			GRADE & FACTOR		
DWELLING UNITS		8	KITCHEN STYLE		1	1. E	4. B	100 %
OTHER UNITS			1. Good 3. Old Style			2. D	5. A	
STORIES		1	BATH(S) STYLE		1	3. C	6. AA	100 %
1. One	4. 1 1/2		1. Good 3. Old Style			SQ. FOOTAGE		
2. Two	5. 1 3/4	1	# ROOMS		6	CONDITION		100 %
3. Three	6. 2 1/2		# BEDROOMS			1. Poor	5. Avg +	
EXTERIOR WALLS		1990	# FULL BATHS		2	2. Fair	6. Good	100 %
1. Clapboard	6. BR./Stone		# HALF BATHS			3. Avg -	7. V Good	
2. WD.SH.	7. Novelty	1	# ADDN FIXTURES		1	4. Avg.	8. Exc.	100 %
3. Comp.	8. AL/Vinyl		# FIREPLACES			ECON. % GOOD		
4. ASB/ASP	9. Other	4	# HEARTHES		1	ECON. CODE		5
5. T1-11			LAYOUT			ENTRANCE CODE		
ROOF SURFACE		1	# ROOFS		3	1. Incomp.	5. CDU	100 %
1. Asphalt	4. Comp.		# BEDROOMS			2. Overbuilt	6. Style	
2. Slate	5. Wood	1	# FULL BATHS		2	3. Delap.	7. Layout	100 %
3. Metal	6. Other		# HALF BATHS			4. Small Size	8. Other	
S/F MASONRY TRIM		1	# ADDN FIXTURES		1	FUNCT. % GOOD		100 %
YEAR BUILT			# FIREPLACES			FUNCT. CODE		
YEAR REMODELED		4	# HEARTHES		1	ECON. % GOOD		100 %
FOUNDATION			LAYOUT			ECON. CODE		
1. Conc.	4. Wood	1	ATTIC		9	1. Location	3. Services	5
2. C Blk	5. Slab		1. 1/4 Fin 4. Full Fin.			ENTRANCE CODE		
3. Br./Stone	6. Piers	4	INT COMP TO EXIT + - -		1	2. Refused	5. Estim.	5
BASEMENT			INSPECTED BY			INFO. CODE		
1. 1/4 3. 3/4 5. Crawl		1	DATE INSPECTED		11/14/05	3. Info Only		5
2. 1/2 4. Full 6. None			WET BASEMENT			INFO. CODE		
BSMT GAR # CARS		1	DATE INSPECTED		11/14/05	1. Owner	4. Agent	5
WET BASEMENT			DATE INSPECTED			INFO. CODE		
1. Dry	3. Wet	DATE INSPECTED		INFO. CODE		2. Relative	5. Estimate	5
2. Damp	9. None	DATE INSPECTED		INFO. CODE		3. Tenant	6. Other	
ADDITIONS, OUTBUILDINGS & IMPROVEMENTS		DATE INSPECTED		INFO. CODE		2. Refused	5. Estim.	5



	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
1.5S/B	4		816			%	%	1. 1S Fr.
1S	1		120			%	%	2. 2S Fr.
BMT	37		120			%	%	3. 3S Fr.
OP	21	2000	72			%	%	4. 1 1/2S Fr.
1.5S/GAR	48	2000	896			%	%	5. 1 3/4S Fr.
WD	68	2000	200			%	%	6. 2 1/2S Fr.
						%	%	Add 10 for Bsmt
						%	%	21. OFF
						%	%	22. EFP
						%	%	23. Garage
						%	%	24. Shed
						%	%	25. Bay Window
						%	%	26. Overhang
						%	%	27. Unf. Bsmt
						%	%	28. Unf. Attic
						%	%	29. Fin. Attic
						%	%	Add 20 for 2 Story
						%	%	61. Carport
						%	%	62. Patio
						%	%	63. Swimming Pool
						%	%	64. Tennis Court
						%	%	65. Stable w/loft
						%	%	66. Greenhouse
						%	%	67. Natatorium
						%	%	68. Wood Deck
						%	%	69. Jacuzzi

PHOTO

NOTES: