


BUILDING RECORD

MAP LOT ACCOUNT NO. 1337 ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING	260	INSULATION		
1. Conv. 8. Split Lev.	1	FIN BSMT GRADE	3	1. Full 4. Minimal	1	
2. Ranch 7. Contemp.			100	2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				UNFINISHED %		%
5. Garrison				GRADE & FACTOR		
DWELLING UNITS	1	HEAT TYPE	5	1. E 4. B	3	
OTHER UNITS	1	1. HW BB 6. Grav. WA		2. D 5. A		
STORIES	2	2. HW CI 7. Electric		3. C 6. AA		
1. One 4. 1 1/2		3. HW Radiant 8. Units		SQ. FOOTAGE		228
2. Two 5. 1 3/4		4. Steam 9. No Heat		CONDITION		6
3. Three 6. 2 1/2		5. FWA	%	1. Poor 5. Avg +	%	
EXTERIOR WALLS	1	COOL TYPE	9	2. Fair 6. Good		
1. Clapboard 6. BR./Stone		1. Central 9. None	%	3. Avg - 7. V Good		
2. WD.SH. 7. Novelty		KITCHEN STYLE	2	4. Avg. 8. Exc.		
3. Comp. 8. AL/Vinyl		1. Good 3. Old Style		PHYS. % GOOD		%
4. ASB/ASP 9. Other		2. Typical 4. Obsolete	2	FUNCT. % GOOD	%	
5. T1-11		BATH(S) STYLE		FUNCT. CODE		
ROOF SURFACE	1	# ROOMS	7	1. Incomp. 5. CDU	%	
1. Asphalt 4. Comp.		# BEDROOMS	3	2. Overbuilt 6. Style		
2. Slate 5. Wood		#FULL BATHS	1	3. Delap. 7. Layout		
3. Metal 6. Other		# HALF BATHS	1	4. Small Size 8. Other		
S/F MASONRY TRIM	1989	# ADDN FIXTURES	1	9. None		
YEAR BUILT	1989	# FIREPLACES	1	ECON. % GOOD	%	
YEAR REMODELED		# HEARTHES		ECON. CODE		
FOUNDATION	1	LAYOUT	1	1. Location 3. Services	3	
1. Conc. 4. Wood		1. Typical 2. In adeq.		2. Encroach 9. None		
2. C Blk 5. Slab		ATTIC	9	ENTRANCE CODE		
3. Br./Stone 6. Piers		1. 1/4 Fin 4. Full Fin.		1. Inspect. 3. Vacant		
BASEMENT	4	2. 1/2 Fin. 5. FV/Stairs		2. Refused 5. Estim.		
1. 1/4 3. 3/4 5. Crawl		3. 3/4 Fin. 9. None		3. Info Only		
2. 1/2 4. Full 6. None		INT COMP TO EXIT + = -		INFO. CODE		
BSMT GAR # CARS		INSPECTED BY	JLD	1. Owner 4. Agent	1	
WET BASEMENT	1	DATE INSPECTED	8/25/05	2. Relative 5. Estimate		
1. Dry 3. Wet				3. Tenant 6. Other		
2. Damp 9. None				2. Refused 5. Estim.		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
DWC	2	1989	896	3.40	6	%	%	1. 1S Fr.
DK	84		84			%	%	2. 2S Fr.
JHD	24		120			%	%	3. 3S Fr.
DK	24		110			%	%	4. 1 1/2S Fr.
						%	%	5. 1 3/4S Fr.
						%	%	6. 2 1/2S Fr.
						%	%	Add 10 for Bsmt
						%	%	21. OFP
						%	%	22. EFP
						%	%	23. Garage
						%	%	24. Shed
						%	%	25. Bay Window
						%	%	26. Overhang
						%	%	27. Unf. Bsmt
						%	%	28. Unf. Attic
						%	%	29. Fin. Attic
						%	%	Add 20 for 2 Story
						%	%	61. Carport
						%	%	62. Patio
						%	%	63. Swimming Pool
						%	%	64. Tennis Court
						%	%	65. Stable w/loft
						%	%	66. Greenhouse
						%	%	67. Natatorium
						%	%	68. Wood Deck
						%	%	69. Jacuzzi

PHOTO

NOTES: Phil Deck is detached from house