




MAP 13 LOT 067-001 ACCOUNT NO. 1499 BUILDING RECORD ADDRESS 999 Sokelin Trail CARD NO.      OF     

<b>BUILDING STYLE</b>		4	<b>S/F BSMT LIVING</b>		1	<b>INSULATION</b>		1
1. Conv.	6. Split Lev.		<b>FIN BSMT GRADE</b>			1. Full	4. Minimal	
2. Ranch	7. Contemp.	4	<b>HEAT TYPE</b>		1	2. Heavy	9. None	%
3. R. Ranch	8. Log		1. HW BB			6. Grav. WA	3. Capped	
4. Cape	9. Other	4	<b>COOL TYPE</b>		9	<b>UNFINISHED %</b>		%
5. Garrison			1. Central			9. None	<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>		8	<b>KITCHEN STYLE</b>		2	1. E	4. B	3
<b>OTHER UNITS</b>			1. Good			3. Old Style	2. D	
<b>STORIES</b>		1	<b>BATH(S) STYLE</b>		2	3. C	6. AA	5
1. One	4. 1 1/2		1. Good			3. Old Style	<b>SQ. FOOTAGE</b>	
2. Two	5. 1 3/4	1	<b># ROOMS</b>		2	<b>CONDITION</b>		%
3. Three	6. 2 1/2		1. Incomp.			5. Avg +	1. Poor	
<b>EXTERIOR WALLS</b>		1	<b># BEDROOMS</b>		2	2. Fair	6. Good	%
1. Clapboard	6. BR./Stone		2. Typical			4. Obsolete	3. Avg -	
2. WD.SH.	7. Novelty	1	<b># FULL BATHS</b>		2	4. Avg.	8. Exc.	%
3. Comp.	8. AL/Vinyl		2. Typical			4. Obsolete	<b>PHYS. % GOOD</b>	
4. ASB/ASP	9. Other	1	<b># HALF BATHS</b>		2	<b>FUNCT. % GOOD</b>		%
5. T1-11			2. Typical			4. Obsolete	<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		1	<b># ADDN FIXTURES</b>		2	1. Incomp.	5. CDU	%
1. Asphalt	4. Comp.		2. Typical			4. Obsolete	2. Overbuilt	
2. Slate	5. Wood	1	<b># FIREPLACES</b>		2	3. Delap.	7. Layout	%
3. Metal	6. Other		2. Typical			4. Obsolete	4. Small Size	
<b>S/F MASONRY TRIM</b>		1	<b># HEARTHES</b>		2	9. None		%
<b>YEAR BUILT</b>			1. Typical			2. In adeq.	<b>ECON. % GOOD</b>	
<b>YEAR REMODELED</b>		1	<b>LAYOUT</b>		2	<b>ECON. CODE</b>		%
<b>FOUNDATION</b>			1. Typical			2. In adeq.	<b>ENTRANCE CODE</b>	
1. Conc.	4. Wood	1	<b>ATTIC</b>		2	1. Inspct.	3. Vacant	%
2. C Blk	5. Stab		1. 1/4 Fin.			4. Full Fin.	2. Refused	
3. Br./Stone	6. Piers	1	<b>INT COMP TO EXIT + = -</b>		2	<b>INFO. CODE</b>		%
<b>BASEMENT</b>			1. 1/2 Fin.			5. FV/Stairs	1. Owner	
1. 1/4	3. 3/4	1	<b>INSPECTED BY</b>		2	2. Relative	5. Estimate	%
2. 1/2	4. Full		1. 3/4 Fin.			9. None	3. Tenant	
<b>BSMT GAR # CARS</b>		1	<b>DATE INSPECTED</b>		2	2. Refused	5. Estim.	%
<b>WET BASEMENT</b>			11.9.05			<b>INFO. CODE</b>		
1. Dry	3. Wet	1			2			%
2. Damp	9. None							



**ADDITIONS, OUTBUILDINGS & IMPROVEMENTS**

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		
						Phys.	Funct.	
DECK	068		496*	3	4	---	---	1. 1S Fr.
Shed	024		80	3	4	---	---	2. 2S Fr.
EFP	022		120	3	4	---	---	3. 3S Fr.
						---	---	4. 1 1/2S Fr.
						---	---	5. 1 3/4S Fr.
						---	---	6. 2 1/2S Fr.
						---	---	Add 10 for Bsmt
						---	---	21. OFP
						---	---	22. EFP
						---	---	23. Garage
						---	---	24. Shed
						---	---	25. Bay Window
						---	---	26. Overhang
						---	---	27. Unf. Bsmt
						---	---	28. Unf. Attic
						---	---	29. Fin. Attic
						---	---	Add 20 for 2 Story
						---	---	61. Carport
						---	---	62. Patio
						---	---	63. Swimming Pool
						---	---	64. Tennis Court
						---	---	65. Stable w/loft
						---	---	66. Greenhouse
						---	---	67. Natatorium
						---	---	68. Wood Deck
						---	---	69. Jacuzzi

11.9.05 - 041

PHOTO

NOTES: 600 - 30 - 30 - 44 20