


BUILDING RECORD

MAP 20 LOT 22 ACCOUNT NO. 1784 ADDRESS _____ CARD NO. ____ OF ____

BUILDING STYLE		S/F BSMT LIVING	<u>0</u>	INSULATION	<u>1</u>
1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison		FIN BSMT GRADE	<u>-</u>	1. Full 4. Minimal 2. Heavy 9. None 3. Capped	
DWELLING UNITS		HEAT TYPE	<u>1</u>	UNFINISHED %	<u>3</u>
1		1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA		GRADE & FACTOR	
OTHER UNITS		COOL TYPE	<u>1</u>	1. E 4. B 2. D 5. A 3. C 6. AA	<u>760</u>
1		1. Central 9. None		SQ. FOOTAGE	<u>760</u>
STORIES		KITCHEN STYLE	<u>2</u>	CONDITION	<u>6</u>
1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2		1. Good 3. Old Style 2. Typical 4. Obsolete		1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	
EXTERIOR WALLS		BATH(S) STYLE	<u>2</u>	PHYS. % GOOD	<u>6</u>
1. Clapboard 6. BR/Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Vinyl 4. ASB/ASP 9. Other 5. T1-11		1. Good 3. Old Style 2. Typical 4. Obsolete		FUNCT. % GOOD	<u>6</u>
ROOF SURFACE		# ROOMS	<u>5</u>	FUNCT. CODE	
1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other		# BEDROOMS	<u>3</u>	1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	
S/F MASONRY TRIM		# FULL BATHS	<u>1</u>	ECON. % GOOD	<u>6</u>
1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers		# HALF BATHS	<u>1</u>	ECON. CODE	
YEAR BUILT		# ADDN FIXTURES	<u>0</u>	1. Location 3. Services 2. Encroach 9. None	
YEAR REMODELED		# FIREPLACES	<u>0</u>	ENTRANCE CODE	<u>1</u>
FOUNDATION		# HEARTHES	<u>0</u>	1. Inspct. 3. Vacant 2. Refused 5. Estim. 3. Info Only	
1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers		LAYOUT		INFO. CODE	<u>1</u>
BASEMENT		1. Typical 2. In adeq.		1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim.	
1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None		ATTIC	<u>9</u>		
BSMT GAR # CARS		1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. Fl/Stairs 3. 3/4 Fin. 9. None			
WET BASEMENT		INT COMP TO EXIT + = -			
1. Dry 3. Wet 2. Damp 9. None		INSPECTED BY	<u>JLO</u>		
		DATE INSPECTED	<u>10/25/05</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWL	001	960	3.00	6	___%	___%	1. 1S Fr.	
ADD	001	224			___%	___%	2. 2S Fr.	
OFF	021	112			___%	___%	3. 3S Fr.	
GAR	023	576			___%	___%	4. 1 1/2S Fr.	
PK	068	130			___%	___%	5. 1 3/4S Fr.	
JHD	024	144		3	___%	___%	6. 2 1/2S Fr.	
PATIO	062	352		4	___%	___%	Add 10 for Bsmt	
ADD BSMT	627	224			___%	___%	21. OFF	
					___%	___%	22. EFP	
					___%	___%	23. Garage	
					___%	___%	24. Shed	
					___%	___%	25. Bay Window	
					___%	___%	26. Overhang	
					___%	___%	27. Unf. Bsmt	
					___%	___%	28. Unf. Attic	
					___%	___%	29. Fin. Attic	
					___%	___%	Add 20 for 2 Story	
					___%	___%	61. Carport	
					___%	___%	62. Patio	
					___%	___%	63. Swimming Pool	
					___%	___%	64. Tennis Court	
					___%	___%	65. Stable w/loft	
					___%	___%	66. Greenhouse	
					___%	___%	67. Natatorium	
					___%	___%	68. Wood Deck	
					___%	___%	69. Jacuzzi	

PHOTO

NOTES: