

BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING		INSULATION	
1. Conv.	6. Split Lev.	0		1. Full	4. Minimal
2. Ranch	7. Contemp.			2. Heavy	9. None
3. R. Ranch	8. Log			3. Capped	
4. Cape	9. Other			UNFINISHED %	
5. Garrison				%	
DWELLING UNITS		HEAT TYPE		GRADE & FACTOR	
1		1. HW BB	6. Grav. WA	1. E	4. B
OTHER UNITS		2. HW CI	7. Electric	2. D	5. A
1		3. HW Radiant	8. Units	3. C	6. AA
STORIES		4. Steam	9. No Heat		
1. One	4. 1 1/2	5. FWA		%	
2. Two	5. 1 3/4	COOL TYPE		SQ. FOOTAGE	
3. Three	6. 2 1/2	1. Central	9. None	1064	
EXTERIOR WALLS				CONDITION	
1. Clapboard	6. BR/Stone			1. Poor	5. Avg +
2. WD.SH.	7. Novelty			2. Fair	6. Good
3. Comp.	8. AL/Vinyl			3. Avg -	7. V Good
4. ASB/ASP	9. Other			4. Avg.	8. Exc.
5. T1-11				%	
ROOF SURFACE		KITCHEN STYLE		PHYS. % GOOD	
1. Asphalt	4. Comp.	1. Good	3. Old Style	%	
2. Slate	5. Wood	2. Typical	4. Obsolete	FUNCT. % GOOD	
3. Metal	6. Other			%	
S/F MASONRY TRIM		BATH(S) STYLE		FUNCT. CODE	
1996		1. Good	3. Old Style		
YEAR BUILT		2. Typical	4. Obsolete		
YEAR REMODELED					
FOUNDATION		# ROOMS			
1. Conc.	4. Wood	4			
2. C Blk	5. Slab	# BEDROOMS			
3. Br./Stone	6. Piers	2			
BASEMENT		# FULL BATHS			
1. 1/4	3. 3/4	1			
2. 1/2	4. Full	# HALF BATHS			
5. Craw	6. None	2			
BSMT GAR # CARS		# ADDN FIXTURES			
0					
WET BASEMENT		# FIREPLACES			
1. Dry	3. Wet				
2. Damp	9. None	# HEARTHES			
		LAYOUT			
		1. Typical		3. Services	
		2. In adeq.		9. None	
		ATTIC		ECON. % GOOD	
		1. 1/4 Fin		%	
		2. 1/2 Fin		ECON. CODE	
		4. Full Fin.			
		5. FV/Stairs			
		3. 3/4 Fin.			
		9. None			
		INT COMP TO EXIT + -			
		INSPECTED BY			
		JLO			
		DATE INSPECTED			
		11/8/05			

14		76	
M/H - 11/18		JLAB	
DWL		1064	
MOBILE HOME		11	
DK 198		18	

ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
DWL	998	1996	1064	3.00	2	---	---	1. 1S Fr. 2. 2S Fr. 3. 3S Fr. 4. 1 1/2S Fr. 5. 1 3/4S Fr. 6. 2 1/2S Fr. Add 10 for Bsmt
DK	068		198		8	---	---	21. OFP 22. EFP
CAR	043		896		8	---	---	23. Garage 24. Shed
DK	068		150		8	---	---	25. Bay Window 26. Overhang
SHD	024		120		2	---	---	27. Unf. Bsmt 28. Unf. Attic
CONC SLAB	103		1064			---	---	29. Fin. Attic Add 20 for 2 Story
						---	---	61. Carport 62. Patio
						---	---	63. Swimming Pool 64. Tennis Court
						---	---	65. Stable w/loft 66. Greenhouse
						---	---	67. Natatorium 68. Wood Deck
						---	---	69. Jacuzzi

PHOTO

NOTES: 2nd story of GARAGE IS IN PROCESS OF BEING FINISHED - HAS 10x15 DK