




<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>		
1. Conv. 8. Split Lev.	2	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	9	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>		
5. Garrison				<b>GRADE &amp; FACTOR</b>		
<b>DWELLING UNITS</b>	1	<b>HEAT TYPE</b>	9	1. E 4. B	2	
<b>OTHER UNITS</b>		1. HW BB 6. Grav. WA		2. D 5. A		
<b>STORIES</b>	1	2. HW CI 7. Electric		3. C 6. AA		
1. One 4. 1 1/2		3. HW Radiant 8. Units		<b>SQ. FOOTAGE</b>		840
2. Two 5. 1 3/4		4. Steam 9. No Heat		<b>CONDITION</b>		
3. Three 6. 2 1/2	5. FWA	1. Poor 5. Avg +				
<b>EXTERIOR WALLS</b>	9 1/2 (Log)	<b>COOL TYPE</b>		2. Fair 6. Good	2	
1. Clapboard 6. BR./Stone		1. Central 9. None		3. Avg - 7. V Good		
2. WD.SH. 7. Novelty				4. Avg. 8. Exc.		
3. Comp. 9. AL/Vinyl		<b>KITCHEN STYLE</b>	3	<b>PHYS. % GOOD</b>		
4. ASB/ASP 9. Other		1. Good 3. Old Style		<b>FUNCT. % GOOD</b>		
5. T1-11	2. Typical 4. Obsolete	<b>FUNCT. CODE</b>				
<b>ROOF SURFACE</b>	1	<b>BATH(S) STYLE</b>	3	1. Incomp. 5. CDU	9 small windows	
1. Asphalt 4. Comp.		1. Good 3. Old Style		2. Overbuilt 6. Style		
2. Slate 5. Wood		2. Typical 4. Obsolete		3. Delap. 7. Layout		
3. Metal 6. Other		<b># ROOMS</b>		4. Small Size 8. Other		
<b>S/F MASONRY TRIM</b>				<b># BEDROOMS</b>		
<b>YEAR BUILT</b>	1948	<b># FULL BATHS</b>	7	<b>ECON. % GOOD</b>		
<b>YEAR REMODELED</b>		<b># HALF BATHS</b>		<b>ECON. CODE</b>		
<b>FOUNDATION</b>	3	<b># ADDN FIXTURES</b>		1. Location 3. Services	5	
1. Conc. 4. Wood		<b># FIREPLACES</b>		2. Encroach 9. None		
2. C Blk 5. Slab		<b># HEARTHES</b>	1	<b>ENTRANCE CODE</b>		
3. Br./Stone 6. Piers	5	<b>LAYOUT</b>		1. Inspct. 3. Vacant	5	
<b>BASEMENT</b>		1. Typical 2. In adeq.		2. Refused 5. Estim.		
1. 1/4 3. 3/4 5. Crawl		<b>ATTIC</b>	9	3. Info Only		
2. 1/2 4. Full 6. None	1. 1/4 Fin 4. Full Fin.	<b>INFO. CODE</b>				
<b>BSMT GAR # CARS</b>	2. 1/2 Fin. 5. Fl/Stairs			1. Owner 4. Agent		
<b>WET BASEMENT</b>	2	3. 3/4 Fin. 9. None	2. Relative 5. Estimate	5		
1. Dry 3. Wet		<b>INT COMP TO EXIT + = -</b>			3. Tenant 6. Other	
2. Damp 9. None		<b>INSPECTED BY</b>	2. Refused 5. Estim.			
		ETJ				
		<b>DATE INSPECTED</b>				
		11-7-05				



**ADDITIONS, OUTBUILDINGS & IMPROVEMENTS**

TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		
					Phys.	Funct.	
EFP	22	1948	198				

- 1. 1S Fr.
- 2. 2S Fr.
- 3. 3S Fr.
- 4. 1 1/2S Fr.
- 5. 1 3/4S Fr.
- 6. 2 1/2S Fr.
- Add 10 for Bsmt
- 21. OFP
- 22. EFP
- 23. Garage
- 24. Shed
- 25. Bay Window
- 26. Overhang
- 27. Unf. Bsmt
- 28. Unf. Attic
- 29. Fin. Attic
- Add 20 for 2 Story
- 61. Carport
- 62. Patio
- 63. Swimming Pool
- 64. Tennis Court
- 65. Stable w/loft
- 66. Greenhouse
- 67. Natatorium
- 68. Wood Deck
- 69. Jacuzzi

PHOTO