


BUILDING RECORD

MAP 32 LOT 71R ACCOUNT NO. 2190 ADDRESS

CARD NO. OF

| | | | | | | |
|---------------------------|------|-------------------------------|----------|---------------------------|-------------------------|--------------------|
| BUILDING STYLE | | S/F BSMT LIVING | | INSULATION | | |
| 1. Conv. 6. Split Lev. | 2 | FIN BSMT GRADE | | 1. Full 4. Minimal | 9 | |
| 2. Ranch 7. Contemp. | | | | 2. Heavy 9. None | | |
| 3. R. Ranch 8. Log | | | | 3. Capped | | |
| 4. Cape 9. Other | | | | UNFINISHED % | | % |
| 5. Garrison | | | | GRADE & FACTOR | | |
| DWELLING UNITS | 1 | HEAT TYPE | | 1. E 4. B | 3 | |
| OTHER UNITS | | 1. HW BB 6. Grav. WA | 9 | 2. D 5. A | | |
| STORIES | 1 | 2. HW Cl 7. Electric | | % | | 3. C 6. AA |
| 1. One 4. 1 1/2 | | 3. HW Radiant 8. Units | | | | SQ. FOOTAGE |
| 2. Two 5. 1 3/4 | | 4. Steam 9. No Heat | | | | CONDITION |
| 3. Three 6. 2 1/2 | | 5. FWA | | | 1. Poor 5. Avg + | |
| EXTERIOR WALLS | 1+2 | COOL TYPE | 9 | 2. Fair 6. Good | 3 | |
| 1. Clapboard 6. BR./Stone | | 1. Central 9. None | | 3. Avg - 7. V Good | | |
| 2. WD.SH. 7. Novelty | | KITCHEN STYLE | | 4. Avg. 8. Exc. | | |
| 3. Comp. 8. AL/Minyl | | 1. Good 3. Old Style | 3 | PHYS. % GOOD | | |
| 4. ASB/ASP 9. Other | | 2. Typical 4. Obsolete | | FUNCT. % GOOD | | |
| 5. T1-11 | | BATH(S) STYLE | | FUNCT. CODE | | |
| ROOF SURFACE | 1 | 1. Good 3. Old Style | 3 | 1. Incomp. 5. CDU | 5 | |
| 1. Asphalt 4. Comp. | | 2. Typical 4. Obsolete | | 2. Overbuilt 6. Style | | |
| 2. Slate 5. Wood | | # ROOMS | 4 | 3. Delap. 7. Layout | | |
| 3. Metal 6. Other | | # BEDROOMS | 1 | 4. Small Size 8. Other | | |
| S/F MASONRY TRIM | 1960 | # FULL BATHS | 1 | 9. None | | |
| YEAR BUILT | 1960 | # HALF BATHS | 0 | ECON. % GOOD | % | |
| YEAR REMODELED | | # ADDN FIXTURES | 6 | ECON. CODE | | |
| FOUNDATION | | # FIREPLACES | 0 | 1. Location 3. Services | 5 | |
| 1. Conc. 4. Wood | | # HEARTHES | 1 | 2. Encroach 9. None | | |
| 2. C Blk 5. Stab | 6 | LAYOUT | 1 | ENTRANCE CODE | | |
| 3. Br./Stone 6. Piers | | 1. Typical 2. In adeq. | | 1. Inspct. 3. Vacant | | |
| BASEMENT | 6 | ATTIC | | 2. Refused 5. Estim. | | |
| 1. 1/4 3. 3/4 5. Crawl | | 1. 1/4 Fin 4. Full Fin. | 9 | 3. Info Only | | |
| 2. 1/2 4. Full 6. None | 6 | 2. 1/2 Fin. 5. FV/Stairs | | | INFO. CODE | |
| BSMT GAR # CARS | | 3. 3/4 Fin. 9. None | | | 1. Owner 4. Agent | |
| WET BASEMENT | 9 | INT COMP TO EXIT + = - | | | 2. Relative 5. Estimate | |
| 1. Dry 3. Wet | | INSPECTED BY | | LB | 3. Tenant 6. Other | |
| 2. Damp 9. None | | DATE INSPECTED | 10/21/05 | 2. Refused 5. Estim. | | |



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

CODES

| | TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD | | |
|------|------|------|-------|-------|------|--------------|--------|--------------------|
| | | | | | | Phys. | Funct. | |
| Shed | 24 | 618 | 48 | | | % | % | 1. 1S Fr. |
| 1st | 01 | | 572 | | | % | % | 2. 2S Fr. |
| FFP | 22 | | 110 | | | % | % | 3. 3S Fr. |
| DK | 68 | | 30 | | | % | % | 4. 1 1/2S Fr. |
| | | | | | | % | % | 5. 1 3/4S Fr. |
| | | | | | | % | % | 6. 2 1/2S Fr. |
| | | | | | | % | % | Add 10 for Bsmt |
| | | | | | | % | % | 21. OFP |
| | | | | | | % | % | 22. EFP |
| | | | | | | % | % | 23. Garage |
| | | | | | | % | % | 24. Shed |
| | | | | | | % | % | 25. Bay Window |
| | | | | | | % | % | 26. Overhang |
| | | | | | | % | % | 27. Unf. Bsmt |
| | | | | | | % | % | 28. Unf. Attic |
| | | | | | | % | % | 29. Fin. Attic |
| | | | | | | % | % | Add 20 for 2 Story |
| | | | | | | % | % | 61. Carport |
| | | | | | | % | % | 62. Patio |
| | | | | | | % | % | 63. Swimming Pool |
| | | | | | | % | % | 64. Tennis Court |
| | | | | | | % | % | 65. Stable w/loft |
| | | | | | | % | % | 66. Greenhouse |
| | | | | | | % | % | 67. Natatorium |
| | | | | | | % | % | 68. Wood Deck |
| | | | | | | % | % | 69. Jacuzzi |

PHOTO

NOTES: