


BUILDING RECORD

MAP 35 LOT 10 ACCOUNT NO. 2291 ADDRESS _____ CARD NO. ____ OF ____

BUILDING STYLE		S/F BSMT LIVING	<u>300</u>	INSULATION	
1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison	<u>2</u>	FIN BSMT GRADE	<u>3</u>	1. Full 4. Minimal 2. Heavy 9. None 3. Capped	<u>1</u>
DWELLING UNITS	<u>1</u>	HEAT TYPE		UNFINISHED %	<u>110</u> %
OTHER UNITS	<u>0</u>	1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA	<u>5</u> %	GRADE & FACTOR	<u>3</u>
STORIES	<u>1</u>	COOL TYPE		1. E 4. B 2. D 5. A 3. C 6. AA	<u>832</u>
1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2		1. Central 9. None	<u>9</u> %	SQ. FOOTAGE	<u>5</u>
EXTERIOR WALLS	<u>2</u>	KITCHEN STYLE		CONDITION	
1. Clapboard 6. BR./Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Vinyl 4. ASB/ASP 9. Other 5. T1-11		1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	<u>9</u> %
ROOF SURFACE	<u>1</u>	BATH(S) STYLE	<u>2</u>	PHYS. % GOOD	<u>5</u> %
1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other		1. Good 3. Old Style 2. Typical 4. Obsolete		FUNCT. % GOOD	<u>5</u> %
S/F MASONRY TRIM	<u>0</u>	# ROOMS	<u>4</u>	FUNCT. CODE	
YEAR BUILT	<u>1959</u>	# BEDROOMS	<u>1</u>	1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	<u>9</u>
YEAR REMODELED		# FULL BATHS		ECON. % GOOD	<u>9</u> %
FOUNDATION	<u>2</u>	# HALF BATHS		ECON. CODE	
1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers		# ADDN FIXTURES		1. Location 3. Services 2. Encroach 9. None	<u>5</u>
BASEMENT	<u>4</u>	# FIREPLACES		ENTRANCE CODE	
1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None		# HEARTHES	<u>1</u>	1. Inspct. 3. Vacant 2. Refused 5. Estim. 3. Info Only	<u>5</u>
BSMT GAR # CARS		LAYOUT		INFO. CODE	<u>5</u>
WET BASEMENT	<u>1</u>	1. Typical 2. In adeq.		1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim.	
1. Dry 3. Wet 2. Damp 9. None		ATTIC			
		1. 1/4 Fin. 4. Full Fin. 2. 1/2 Fin. 5. Fl/Stairs 3. 3/4 Fin. 9. None	<u>9</u>		
		INT COMP TO EXIT + = -	<u>=</u>		
		INSPECTED BY	<u>AJA</u>		
		DATE INSPECTED	<u>3/12/06</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
WO	068	1959	409	3.00	3	---	---	1. 1S Fr.
WO	068	1959	64	3.00	3	---	---	2. 2S Fr.
Garage	023	1959	672	3.00	3	---	---	3. 3S Fr.
Shed	024	1959	96	3.00	3	---	---	4. 1 1/2S Fr.
								5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								Add 10 for Bsmt
								21. OFF
								22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								Add 20 for 2 Story
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES: