




MAP 42. LOT A188 ACCOUNT NO. 2575 BUILDING RECORD ADDRESS \_\_\_\_\_ CARD NO. \_\_\_\_ OF \_\_\_\_

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	<u>800</u>	<b>INSULATION</b>		
1. Conv. 6. Split Lev.	3	<b>FIN BSMT GRADE</b>	<u>3</u>	1. Full 4. Minimal	1	
2. Ranch 7. Contemp.			<u>100</u>	2. Heavy 9. None		
3. R. Ranch 8. Log		<b>HEAT TYPE</b>		3. Capped		
4. Cape 9. Other		1. HW BB 6. Grav. WA	1	<b>UNFINISHED %</b>		____%
5. Garrison		2. HW CI 7. Electric		<b>GRADE &amp; FACTOR</b>		<u>10</u>
<b>DWELLING UNITS</b>	3. HW Radiant 8. Units	1. E 4. B		3+		
<b>OTHER UNITS</b>	4. Steam 9. No Heat	2. D 5. A				
<b>STORIES</b>	5. FWA	3. C 6. AA				
1. One 4. 1 1/2	1	<b>COOL TYPE</b>		<b>SQ. FOOTAGE</b>	<u>0864</u>	
2. Two 5. 1 3/4	1	1. Central 9. None	<u>9</u>	<b>CONDITION</b>	5	
3. Three 6. 2 1/2		<b>KITCHEN STYLE</b>		1. Poor 5. Avg +		
<b>EXTERIOR WALLS</b>		1. Good 3. Old Style	2	2. Fair 6. Good		
1. Clapboard 6. BR./Stone		2. Typical 4. Obsolete		3. Avg - 7. V Good		
2. WD.SH. 7. Novelty		<b>BATH(S) STYLE</b>	2	4. Avg. 8. Exc.		____%
3. Comp. 8. AL/Minyl	1. Good 3. Old Style	<b>PHYS. % GOOD</b>		____%		
4. ASB/ASP 9. Other	2. Typical 4. Obsolete	<b># ROOMS</b>	<u>9</u>	<b>FUNCT. % GOOD</b>	____%	
<b>ROOF SURFACE</b>	1	<b># BEDROOMS</b>	<u>2</u>	<b>FUNCT. CODE</b>	9	
1. Asphalt 4. Comp.	1	<b># FULL BATHS</b>	<u>1</u>	1. Incomp. 5. CDU		
2. Slate 5. Wood		<b># HALF BATHS</b>	<u>1</u>	2. Overbuilt 6. Style		
3. Metal 6. Other		<b># ADDN FIXTURES</b>	<u>0</u>	3. Delap. 7. Layout		
<b>S/F MASONRY TRIM</b>		<b># FIREPLACES</b>	<u>0</u>	4. Small Size 8. Other		
<b>YEAR BUILT</b>		<u>1989</u>	<b># HEARTHES</b>	<u>1</u>	9. None	
<b>YEAR REMODELED</b>		<b>LAYOUT</b>		<b>ECON. % GOOD</b>	____%	
<b>FOUNDATION</b>		1. Typical 2. In adeq.	<u>1</u>	<b>ECON. CODE</b>	9	
1. Conc. 4. Wood	1	<b>ATTIC</b>		1. Location 3. Services		
2. C Blk 5. Stab		1. 1/4 Fin 4. Full Fin.	9	2. Encroach 9. None		
3. Br./Stone 6. Piers		2. 1/2 Fin. 5. Fl/Stairs		<b>ENTRANCE CODE</b>		
<b>BASEMENT</b>		3. 3/4 Fin. 9. None		1. Inspt. 3. Vacant		
1. 1/4 3. 3/4 5. Crawl		4	<b>INT COMP TO EXIT + = -</b>		2. Refused 5. Estim.	
2. 1/2 4. Full 6. None	1	<b>INSPECTED BY</b>	<u>RAK</u>	3. Info Only		
<b>BSMT GAR # CARS</b>		<u>0</u>	<b>DATE INSPECTED</b>	<u>7-1-05</u>	<b>INFO. CODE</b>	
<b>WET BASEMENT</b>					1. Owner 4. Agent	
1. Dry 3. Wet		1			2. Relative 5. Estimate	
2. Damp 9. None					3. Tenant 6. Other	
				2. Refused 5. Estim.		



**ADDITIONS, OUTBUILDINGS & IMPROVEMENTS**

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
<u>15</u>	<u>001</u>	<u>1989</u>	<u>0864</u>	---	---	___%	___%	1. 1S Fr.
<u>DK</u>	<u>028</u>	---	<u>0010</u>	---	---	___%	___%	2. 2S Fr.
<u>OH</u>	<u>026</u>	---	<u>0030</u>	---	---	___%	___%	3. 3S Fr.
								4. 1 1/2S Fr.
								5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								<b>Add 10 for Bsmt</b>
								21. OFP
								22. EFP
								23. Garage
								24. Shed
<u>shed</u>	<u>024</u>	---	<u>0096</u>	---	<u>2</u>	___%	___%	25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								<b>Add 20 for 2 Story</b>
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES: