


1E

BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

| | | | | | | | |
|-------------------------|---------------|------------------------|--|---------------------------|------------|-------------|--|
| BUILDING STYLE | | S/F BSMT LIVING | | INSULATION | | 1 | |
| 1. Conv. | 6. Split Lev. | FIN BSMT GRADE | | 1. Full | 4. Minimal | | |
| 2. Ranch | 7. Contemp. | | | 2. Heavy | 9. None | | |
| 3. R. Ranch | 8. Log | | | 3. Capped | | | |
| 4. Cape | 9. Other | | | UNFINISHED % | | | |
| 5. Garrison | | | | GRADE & FACTOR | | 3 | |
| DWELLING UNITS | | | | 1. E | | 4. B | |
| OTHER UNITS | | | | 2. D | | 5. A | |
| STORIES | | 100 % | | 3. C | | 6. AA | |
| 1. One | 4. 1 1/2 | | | SQ. FOOTAGE | | | |
| 2. Two | 5. 1 3/4 | | | CONDITION | | 4 | |
| 3. Three | 6. 2 1/2 | | | 1. Poor | | 5. Avg + | |
| EXTERIOR WALLS | | 9 % | | 2. Fair | | 6. Good | |
| 1. Clapboard | 6. BR./Stone | 2 | | 3. Avg - | | 7. V Good | |
| 2. WD.SH. | 7. Novelty | | | 4. Avg. | | 8. Exc. | |
| 3. Comp. | 8. AL/Vinyl | 2 | | PHYS. % GOOD | | 100 % | |
| 4. ASB/ASP | 9. Other | | | FUNCT. % GOOD | | 100 % | |
| 5. T1-11 | | | | FUNCT. CODE | | | |
| ROOF SURFACE | | 3 | | 1. Incomp. | | 5. CDU | |
| 1. Asphalt | 4. Comp. | 2 | | 2. Overbuilt | | 6. Style | |
| 2. Slate | 5. Wood | 2 | | 3. Delap. | | 7. Layout | |
| 3. Metal | 6. Other | 2 | | 4. Small Size | | 8. Other | |
| S/F MASONRY TRIM | | 4 | | 9. None | | | |
| YEAR BUILT | | 400 | | ECON. % GOOD | | 100 % | |
| YEAR REMODELED | | 1987 | | ECON. CODE | | | |
| FOUNDATION | | 1 | | 1. Location | | 3. Services | |
| 1. Conc. | 4. Wood | | | 2. Encroach | | 9. None | |
| 2. C Blk | 5. Slab | | | ENTRANCE CODE | | 5 | |
| 3. Br./Stone | 6. Piers | | | 1. Inspct. | | 3. Vacant | |
| BASEMENT | | 4 | | 2. Refused | | 5. Estim. | |
| 1. 1/4 | 3. 3/4 | | | 3. Info Only | | | |
| 2. 1/2 | 4. Full | | | INFO. CODE | | 5 | |
| 5. Crawl | 6. None | | | 1. Owner | | 4. Agent | |
| BSMT GAR # CARS | | KSH | | 2. Relative | | 5. Estimate | |
| WET BASEMENT | | 6/30/05 | | 3. Tenant | | 6. Other | |
| 1. Dry | 3. Wet | | | 2. Refused | | 5. Estim. | |
| 2. Damp | 9. None | | | | | | |



PHOTO

X = SEWER LINES

896

| ADDITIONS, OUTBUILDINGS & IMPROVEMENTS | | | | | | PERCENT GOOD | | CODES |
|--|------|-------|-------|------|-------|--------------|--------------------|-------|
| TYPE | YEAR | UNITS | GRADE | COND | Phys. | Funct. | | |
| 15/16 WA | 4 | 896 | | | % | % | 1. 1S Fr. | |
| 15 | 1 | 164 | | | % | % | 2. 2S Fr. | |
| 15 | 1 | 336 | | | % | % | 3. 3S Fr. | |
| BMT | 37 | 336 | | | % | % | 4. 1 1/2S Fr. | |
| WD | 68 | 324 | | | % | % | 5. 1 3/4S Fr. | |
| SHED | 24 | 40 | | | % | % | 6. 2 1/2S Fr. | |
| 155 GAR | 48 | 572 | | | % | % | Add 10 for Bsmt | |
| WD | 68 | 33 | | | % | % | 21. OFF | |
| | | | | | % | % | 22. EFP | |
| | | | | | % | % | 23. Garage | |
| | | | | | % | % | 24. Shed | |
| | | | | | % | % | 25. Bay Window | |
| | | | | | % | % | 26. Overhang | |
| | | | | | % | % | 27. Unf. Bsmt | |
| | | | | | % | % | 28. Unf. Attic | |
| | | | | | % | % | 29. Fin. Attic | |
| | | | | | % | % | Add 20 for 2 Story | |
| | | | | | % | % | 61. Carport | |
| | | | | | % | % | 62. Patio | |
| | | | | | % | % | 63. Swimming Pool | |
| | | | | | % | % | 64. Tennis Court | |
| | | | | | % | % | 65. Stable w/oft | |
| | | | | | % | % | 66. Greenhouse | |
| | | | | | % | % | 67. Natatorium | |
| | | | | | % | % | 68. Wood Deck | |
| | | | | | % | % | 69. Jacuzzi | |

NOTES: EXT. GAR UNFINISHED ONLY THE MAIN HOUSE IS CLAPBOARD (1994)