


BUILDING RECORD

MAP 47 LOT 136 ACCOUNT NO. 3875 ADDRESS _____ CARD NO. ____ OF ____

| | | | | | |
|---|----------------------|--|--|--|-------------|
| BUILDING STYLE 1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison | <u>2</u> | S/F BSMT LIVING FIN BSMT GRADE | <u>0</u> | INSULATION 1. Full 4. Minimal 2. Heavy 9. None 3. Capped | <u>1</u> |
| DWELLING UNITS | | HEAT TYPE 1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA | <u>5</u> | UNFINISHED % GRADE & FACTOR 1. E 4. B 2. D 5. A 3. C 6. AA | <u>3</u> |
| OTHER UNITS | | COOL TYPE 1. Central 9. None | <u>9</u> | SQ. FOOTAGE CONDITION 1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc. | <u>1008</u> |
| STORIES 1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2 | <u>1</u> | KITCHEN STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete | <u>2</u> | PHYS. % GOOD FUNCT. % GOOD FUNCT. CODE | <u>6</u> |
| EXTERIOR WALLS 1. Clapboard 6. BR./Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Vinyl 4. ASB/ASP 9. Other 5. T1-11 | <u>2</u> | BATH(S) STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete | <u>2</u> | # ROOMS 1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None | <u>9</u> |
| ROOF SURFACE 1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other | <u>1</u> | # BEDROOMS # FULL BATHS # HALF BATHS | <u>3</u> <u>1</u> <u>1</u> | ECON. % GOOD ECON. CODE 1. Location 3. Services 2. Encroach 9. None | <u>9</u> |
| S/F MASONRY TRIM | | # ADDN FIXTURES # FIREPLACES # HEARTHES | | ENTRANCE CODE 1. Inspct. 3. Vacant 2. Refused 5. Estim. 3. Info Only | <u>5</u> |
| YEAR BUILT YEAR REMODELED | <u>1969</u> | LAYOUT 1. Typical 2. In adeq. ATTIC 1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. FV/Stairs 3. 3/4 Fin. 9. None | <u>1</u> <u>9</u> | INFO. CODE 1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim. | <u>5</u> |
| FOUNDATION 1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers | <u>2</u> | INT COMP TO EXIT + - - INSPECTED BY DATE INSPECTED | <u>1</u> <u>RAK</u> <u>2-10-06</u> | | <u>5</u> |
| BASEMENT 1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None | <u>3</u> | | | | |
| BSMT GAR # CARS WET BASEMENT 1. Dry 3. Wet 2. Damp 9. None | <u>0</u> <u>1</u> | | | | |



25 Skylites

ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

| | TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD | | CODES |
|--------------|-----------|-------------|-------------|-------|------|--------------|--------|--------------------|
| | | | | | | Phys. | Funct. | |
| <u>1 1/2</u> | <u>L</u> | <u>1969</u> | <u>1008</u> | | | ___ % | ___ % | 1. 1S Fr. |
| <u>OP</u> | <u>21</u> | | <u>24</u> | | | ___ % | ___ % | 2. 2S Fr. |
| | | | | | | ___ % | ___ % | 3. 3S Fr. |
| | | | | | | ___ % | ___ % | 4. 1 1/2S Fr. |
| | | | | | | ___ % | ___ % | 5. 1 3/4S Fr. |
| | | | | | | ___ % | ___ % | 6. 2 1/2S Fr. |
| | | | | | | ___ % | ___ % | Add 10 for Bsmt |
| | | | | | | ___ % | ___ % | 21. OFF |
| | | | | | | ___ % | ___ % | 22. EFP |
| | | | | | | ___ % | ___ % | 23. Garage |
| | | | | | | ___ % | ___ % | 24. Shed |
| | | | | | | ___ % | ___ % | 25. Bay Window |
| | | | | | | ___ % | ___ % | 26. Overhang |
| | | | | | | ___ % | ___ % | 27. Unf. Bsmt |
| | | | | | | ___ % | ___ % | 28. Unf. Attic |
| | | | | | | ___ % | ___ % | 29. Fin. Attic |
| | | | | | | ___ % | ___ % | Add 20 for 2 Story |
| | | | | | | ___ % | ___ % | 61. Catport |
| | | | | | | ___ % | ___ % | 62. Patio |
| | | | | | | ___ % | ___ % | 63. Swimming Pool |
| | | | | | | ___ % | ___ % | 64. Tennis Court |
| | | | | | | ___ % | ___ % | 65. Stable w/loft |
| | | | | | | ___ % | ___ % | 66. Greenhouse |
| | | | | | | ___ % | ___ % | 67. Natatorium |
| | | | | | | ___ % | ___ % | 68. Wood Deck |
| | | | | | | ___ % | ___ % | 69. Jacuzzi |

PHOTO

NOTES:

Shed
Shed