


3877

BUILDING RECORD

MAP 47 LOT 138 ACCOUNT NO. 400 ^{est.} ADDRESS _____ CARD NO. _____ OF _____

BUILDING STYLE 1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison	<u>2</u>	S/F BSMT LIVING FIN BSMT GRADE	<u>100</u>	INSULATION 1. Full 4. Minimal 2. Heavy 9. None 3. Capped	<u>1</u>
DWELLING UNITS		HEAT TYPE 1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA	<u>8</u>	UNFINISHED %	<u> </u>
OTHER UNITS		COOL TYPE 1. Central 9. None	<u>9</u>	GRADE & FACTOR 1. E 4. B 2. D 5. A 3. C 6. AA	<u>3</u>
STORIES 1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2	<u>1</u>	KITCHEN STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	SQ. FOOTAGE	<u>672</u>
EXTERIOR WALLS 1. Clapboard 6. BR./Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Vinyl 4. ASB/ASP 9. Other 5. T1-11	<u>8</u>	BATH(S) STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	CONDITION 1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	<u>6</u>
ROOF SURFACE 1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other	<u>1</u>	# ROOMS	<u> </u>	PHYS. % GOOD	<u> </u>
S/F MASONRY TRIM		# BEDROOMS	<u>2</u>	FUNCT. % GOOD	<u> </u>
YEAR BUILT	<u>1979</u>	# FULL BATHS	<u>1</u>	FUNCT. CODE 1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	<u>9</u>
YEAR REMODELED		# HALF BATHS	<u> </u>	ECON. % GOOD	<u> </u>
FOUNDATION 1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers	<u>1</u>	# ADDN FIXTURES	<u> </u>	ECON. CODE 1. Location 3. Services 2. Encroach 9. None	<u>9</u>
BASEMENT 1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None	<u>4</u>	# FIREPLACES	<u> </u>	ENTRANCE CODE 1. Inspect. 3. Vacant 2. Refused 5. Estim. 3. Info Only	<u>5</u>
BSMT GAR # CARS	<u>0</u>	# HEARTHES	<u> </u>	INFO. CODE 1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 4. Refused 5. Estim.	<u>5</u>
WET BASEMENT 1. Dry 3. Wet 2. Damp 9. None	<u>1</u>	LAYOUT 1. Typical 2. In adeg.	<u>1</u>		
		ATTIC 1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. FV/Stairs 3. 3/4 Fin. 9. None	<u>9</u>		
		INT COMP TO EXIT + = -	<u> </u>		
		INSPECTED BY	<u>NAK</u>		
		DATE INSPECTED	<u>2-10-06</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
<u>15</u>	<u>1</u>	<u>1979</u>	<u>672</u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	1. 1S Fr. 2. 2S Fr. 3. 3S Fr. 4. 1 1/2S Fr. 5. 1 3/4S Fr. 6. 2 1/2S Fr.
<u>DK</u>	<u>68</u>	<u> </u>	<u>264</u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	Add 10 for Bsmt 21. OFF 22. EFP 23. Garage 24. Shed 25. Bay Window 26. Overhang 27. Unf. Bsm 28. Unf. Attic 29. Fin. Attic
<u>PTO</u>	<u>62</u>	<u> </u>	<u>258</u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	Add 20 for 2 Story 81. Carport 82. Patio 83. Swimming Pool 84. Tennis Court 85. Stable w/loft 86. Greenhouse 87. Natatorium 88. Wood Deck 89. Jacuzzi
<u>shed</u>	<u>24</u>	<u> </u>	<u>120</u>	<u>4</u>	<u>4</u>	<u> </u>	<u> </u>	

PHOTO

NOTES: