



MAP 52 LOT 25


ACCOUNT NO.

BUILDING RECORD

ADDRESS

CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	0	<b>INSULATION</b>		
1. Conv. 6. Split Lev.	2	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>		%
5. Garrison				<b>GRADE &amp; FACTOR</b>		
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>	MONITOR 8	1. E 4. B	3 960	
<b>OTHER UNITS</b>		1. HW BB 6. Grav. WA		2. D 5. A		
<b>STORIES</b>	1	2. HW CI 7. Electric		3. C 6. AA		
1. One 4. 1 1/2		3. HW Radiant 8. Units		<b>SQ. FOOTAGE</b>		
2. Two 5. 1 3/4		4. Steam 9. No Heat		<b>CONDITION</b>		
3. Three 8. 2 1/2		5. FWA	9 %	1. Poor 5. Avg +	5	
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>		2. Fair 6. Good		
1. Clapboard 6. BR./Stone	8	1. Central 9. None	9 %	3. Avg - 7. V Good		
2. WD.SH. 7. Novelty				4. Avg. 8. Exc.		
3. Comp. 8. AL/Vinyl				<b>PHYS. % GOOD</b>		%
4. ASB/ASP 9. Other				<b>FUNCT. % GOOD</b>	%	
5. T1-11				<b>FUNCT. CODE</b>		
<b>ROOF SURFACE</b>		<b>KITCHEN STYLE</b>	2	1. Incomp. 5. CDU	9	
1. Asphalt 4. Comp.	1	1. Good 3. Old Style		2. Overbuilt 6. Style		
2. Slate 5. Wood			2. Typical 4. Obsolete			3. Delap. 7. Layout
3. Metal 6. Other			<b>BATH(S) STYLE</b>	2		4. Small Size 8. Other
<b>S/F MASONRY TRIM</b>			1. Good 3. Old Style			9. None
<b>YEAR BUILT</b>		1975	2. Typical 4. Obsolete		<b>ECON. % GOOD</b>	%
<b>YEAR REMODELED</b>		<b># ROOMS</b>	3	<b>ECON. CODE</b>		
<b>FOUNDATION</b>		<b># BEDROOMS</b>		1. Location 3. Services	9	
1. Conc. 4. Wood	1	<b># FULL BATHS</b>		2. Encroach 9. None		
2. C Blk 5. Stab			<b># HALF BATHS</b>			<b>ENTRANCE CODE</b>
3. Br./Stone 6. Piers			<b># ADDN FIXTURES</b>			1. Inspct. 3. Vacant
<b>BASEMENT</b>			<b># FIREPLACES</b>			2. Refused 5. Estim.
1. 1/4 3. 3/4 5. Crawl		4	<b># HEARTHES</b>		3. Info Only	
2. 1/2 4. Full 6. None		<b>LAYOUT</b>	1	<b>INFO. CODE</b>		
<b>BSMT GAR # CARS</b>	9	1. Typical 2. In adeg.		1. Owner 4. Agent	1	
<b>WET BASEMENT</b>	1	<b>ATTIC</b>		2. Relative 5. Estimate		
1. Dry 3. Wet		1. 1/4 Fin 4. Full Fin.	9	3. Tenant 6. Other		
2. Damp 9. None		2. 1/2 Fin. 5. Fl/Stairs		2. Refused 5. Estim.		
		3. 3/4 Fin. 9. None				
		<b>INT COMP TO EXIT + - -</b>				
		<b>INSPECTED BY</b>	RAX			
		<b>DATE INSPECTED</b>	10-20-05			



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		
						Phys.	Funct.	
15	001	1975	960					1. 1S Fr.
EFP	022		120					2. 2S Fr.
GAR	023		576					3. 3S Fr.
								4. 1 1/2S Fr.
								5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								Add 10 for Bsmt
								21. OFP
								22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								Add 20 for 2 Story
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/toft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES:

① shed  
② shed