


BUILDING RECORD

MAP LOT ACCOUNT NO. 4386 ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING	<u>2</u>	INSULATION	
1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison	<u>2</u>	FIN BSMT GRADE	<u>2</u>	1. Full 4. Minimal 2. Heavy 9. None 3. Capped	<u>1</u>
DWELLING UNITS	<u>1</u>	HEAT TYPE		UNFINISHED %	%
OTHER UNITS	<u>0</u>	1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA	<u>1</u>	GRADE & FACTOR	
STORIES		COOL TYPE		1. E 4. B 2. D 5. A 3. C 6. AA	<u>3</u>
1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2	<u>1</u>	1. Central 9. None	<u>9</u>	SQ. FOOTAGE	<u>1512</u>
EXTERIOR WALLS		KITCHEN STYLE		CONDITION	
1. Clapboard 6. BR./Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Mvnyl 4. ASB/ASP 9. Other 5. T1-11	<u>8</u>	1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	<u>7</u>
ROOF SURFACE		BATH(S) STYLE		PHYS. % GOOD	%
1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other	<u>1</u>	1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	FUNCT. % GOOD	%
S/F MASONRY TRIM		# ROOMS	<u>6</u>	FUNCT. CODE	
1. Conc. 4. Comp. 2. State 5. Wood 3. Metal 6. Other	<u>2001</u>	# BEDROOMS	<u>3</u>	1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	
YEAR BUILT		# FULL BATHS	<u>2</u>	ECON. % GOOD	%
YEAR REMODELED		# HALF BATHS		ECON. CODE	
FOUNDATION		# ADDN FIXTURES	<u>0</u>	1. Location 3. Services 2. Encroach 9. None	
1. Conc. 4. Wood 2. C Blk 5. Stab 3. Br./Stone 6. Piers	<u>1</u>	# FIREPLACES	<u>0</u>	ENTRANCE CODE	
BASEMENT		# HEARTHES	<u>0</u>	1. Inspect. 3. Vacant 2. Refused 5. Estim. 3. Info Only	<u>3</u>
1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None	<u>4</u>	LAYOUT		INFO. CODE	
BSMT GAR # CARS		1. Typical 2. In adeq.	<u>1</u>	1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim.	<u>1</u>
WET BASEMENT		ATTIC			
1. Dry 3. Wet 2. Damp 9. None	<u>1</u>	1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. Fl/Stairs 3. 3/4 Fin. 9. None	<u>9</u>		
		INT COMP TO EXIT + = -			
		INSPECTED BY	<u>JLO</u>		
		DATE INSPECTED	<u>11/17/05</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWL	001	2001	1512	3.00	7	___%	___%	1. 1S Fr. 2. 2S Fr. 3. 3S Fr. 4. 1 1/2S Fr. 5. 1 3/4S Fr. 6. 2 1/2S Fr. Add 10 for Bsmt
DK	068		310		7	___%	___%	21. OFF 22. EFP 23. Garage 24. Shed 25. Bay Window 26. Overhang 27. Unf. Bsmt 28. Unf. Attic 29. Fin. Attic Add 20 for 2 Story
						___%	___%	61. Carport 62. Patio 63. Swimming Pool 64. Tennis Court 65. Stable w/loft 66. Greenhouse 67. Natatorium 68. Wood Deck 69. Jacuzzi

PHOTO

NOTES: