




1228?

BUILDING RECORD

MAP 11 LOT 41 ACCOUNT NO. 01-APT-GAR ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>		
1. Conv. 6. Split Lev.	2	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>		%
5. Garrison				<b>GRADE &amp; FACTOR</b>		
<b>DWELLING UNITS</b>	1	<b>HEAT TYPE</b>		1. E 4. B	3	
<b>OTHER UNITS</b>	1	1. HW BB 6. Grav. WA	1	2. D 5. A		
<b>STORIES</b>		2. HW CI 7. Electric		3. C 6. AA		
1. One 4. 1 1/2	1	3. HW Radiant 8. Units		<b>SQ. FOOTAGE</b>		690
2. Two 5. 1 3/4				<b>CONDITION</b>		
3. Three 6. 2 1/2				1. Poor 5. Avg +	6	
<b>EXTERIOR WALLS</b>		2. Typical 4. Obsolete	2. Fair 6. Good			
1. Clapboard 6. BR./Stone	8	<b>KITCHEN STYLE</b>	3. Avg - 7. V Good			
2. WD.SH. 7. Novelty		1. Good 3. Old Style	4. Avg. 8. Exc.	%		
3. Comp. 8. AL/Vinyl		2. Typical 4. Obsolete	<b>PHYS. % GOOD</b>	%		
4. ASB/ASP 9. Other		<b>BATH(S) STYLE</b>	1. Good 3. Old Style	<b>FUNCT. % GOOD</b>	%	
5. T1-11		2. Typical 4. Obsolete	<b># ROOMS</b>	<b>FUNCT. CODE</b>		
<b>ROOF SURFACE</b>		<b># BEDROOMS</b>	1. Incomp. 5. CDU	2		
1. Asphalt 4. Comp.	1	<b># FULL BATHS</b>	2. Overbuilt 6. Style			
2. Slate 5. Wood		<b># HALF BATHS</b>	3. Delap. 7. Layout			
3. Metal 6. Other		0	4. Small Size 8. Other			
<b>S/F MASONRY TRIM</b>			<b># ADDN FIXTURES</b>		9. None	
<b>YEAR BUILT</b>		1993	<b># FIREPLACES</b>	<b>ECON. % GOOD</b>	%	
<b>YEAR REMODELED</b>		<b># HEARTHES</b>	<b>ECON. CODE</b>			
<b>FOUNDATION</b>		<b>LAYOUT</b>	1. Location 3. Services	1		
1. Conc. 4. Wood	5	1. Typical 2. In adeq.	2. Encroach 9. None			
2. C Blk 5. Stab		<b>ATTIC</b>	<b>ENTRANCE CODE</b>			
3. Br./Stone 6. Piers		1. 1/4 Fin 4. Full Fin.	1. Inspct. 3. Vacant		3	
<b>BASEMENT</b>		2. 1/2 Fin. 5. F/Stairs	2. Refused 5. Estim.			
1. 1/4 3. 3/4 5. Crawl		9	3. Info Only			
2. 1/2 4. Full 6. None		<b>INFO. CODE</b>				
<b>BSMT GAR # CARS</b>		<b>INSPECTED BY</b>	1. Owner 4. Agent	1		
<b>WET BASEMENT</b>		JLO	2. Relative 5. Estimate			
1. Dry 3. Wet	9	<b>DATE INSPECTED</b>	3. Tenant 6. Other			
2. Damp 9. None		8/25/05	2. Refused 5. Estim.			



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
1st Flr	1	690	3.00	6	%	%	1. 1S Fr.	
GAR	23	260			%	%	2. 2S Fr.	
					%	%	3. 3S Fr.	
					%	%	4. 1 1/2S Fr.	
					%	%	5. 1 3/4S Fr.	
					%	%	6. 2 1/2S Fr.	
					%	%	Add 10 for Bsmt	
					%	%	21. OFP	
					%	%	22. EFP	
					%	%	23. Garage	
					%	%	24. Shed	
					%	%	25. Bay Window	
					%	%	26. Overhang	
					%	%	27. Unf. Bsmt	
					%	%	28. Unf. Attic	
					%	%	29. Fin. Attic	
					%	%	Add 20 for 2 Story	
					%	%	61. Carport	
					%	%	62. Patio	
					%	%	63. Swimming Pool	
					%	%	64. Tennis Court	
					%	%	65. Stable w/loft	
					%	%	66. Greenhouse	
					%	%	67. Natatorium	
					%	%	68. Wood Deck	
					%	%	69. Jacuzzi	

PHOTO

NOTES: OWNER INDICATES APT AREA WILL BE CHANGED TO PART OF GARAGE