


CRAY

BUILDING RECORD

MAP LOT ACCOUNT NO. 1381 ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING	200	INSULATION	
1. Conv.	6. Split Lev.	FIN BSMT GRADE	3	1. Full	4. Minimal
2. Ranch	7. Contemp.		100	2. Heavy	9. None
3. R. Ranch	8. Log	HEAT TYPE		3. Capped	
4. Cape	9. Other	1. HW BB	1	UNFINISHED %	%
5. Garrison		2. HW CI		GRADE & FACTOR	
DWELLING UNITS		3. HW Radiant		1. E	4. B
OTHER UNITS		4. Steam		2. D	5. A
STORIES		5. FWA	%	3. C	6. AA
1. One	4. 1 1/2	COOL TYPE		SQ. FOOTAGE	280
2. Two	5. 1 3/4	1. Central	9	CONDITION	
3. Three	6. 2 1/2		%	1. Poor	5. Avg +
EXTERIOR WALLS		KITCHEN STYLE		2. Fair	6. Good
1. Clapboard	6. BR./Stone	1. Good	2	3. Avg -	7. V Good
2. WD.SH.	7. Novelty	2. Typical		4. Avg.	8. Exc.
3. Comp.	8. AL/Mvnyl	BATH(S) STYLE		PHYS. % GOOD	%
4. ASB/ASP	9. Other	1. Good	2	FUNCT. % GOOD	%
5. T1-11		2. Typical		FUNCT. CODE	
ROOF SURFACE		# ROOMS	4	1. Incomp.	5. CDU
1. Asphalt	4. Comp.	# BEDROOMS	3	2. Overbuilt	6. Style
2. Slate	5. Wood	# FULL BATHS	1	3. Delap.	7. Layout
3. Metal	6. Other	# HALF BATHS	0	4. Small Size	8. Other
S/F MASONRY TRIM		# ADDN FIXTURES	0	9. None	
YEAR BUILT		# FIREPLACES	0	ECON. % GOOD	%
YEAR REMODELED		# HEARTHES	0	ECON. CODE	
FOUNDATION		LAYOUT		1. Location	3. Services
1. Conc.	4. Wood	1. Typical	1	2. Encroach	9. None
2. C Blk	5. Slab	ATTIC		ENTRANCE CODE	
3. Br./Stone	6. Piers	1. 1/4 Fin	9	1. Inspct.	3. Vacant
BASEMENT		2. 1/2 Fin.		2. Refused	5. Estim.
1. 1/4	3. 3/4	3. 3/4 Fin.		3. Info Only	
2. 1/2	4. Full	INT COMP TO EXIT + - -		INFO. CODE	
5. Crawl	6. None	INSPECTED BY	JLW	1. Owner	4. Agent
BSMT GAR # CARS		DATE INSPECTED	9/1/05	2. Relative	5. Estimate
WET BASEMENT				3. Tenant	6. Other
1. Dry	3. Wet			2. Refused	5. Estim.
2. Damp	9. None				



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWL	1	1980	960	3.00	7	%	%	1. 1S Fr.
DK	68		80	3.00	5	%	%	2. 2S Fr.
						%	%	3. 3S Fr.
						%	%	4. 1 1/2S Fr.
						%	%	5. 1 3/4S Fr.
						%	%	6. 2 1/2S Fr.
						%	%	Add 10 for Bsmt
						%	%	21. OFF
						%	%	22. EFP
						%	%	23. Garage
						%	%	24. Shed
						%	%	25. Bay Window
						%	%	26. Overhang
						%	%	27. Unf. Bsmt
						%	%	28. Unf. Attic
						%	%	29. Fin. Attic
						%	%	Add 20 for 2 Story
						%	%	61. Carport
						%	%	62. Patio
						%	%	63. Swimming Pool
						%	%	64. Tennis Court
						%	%	65. Stable w/loft
						%	%	66. Greenhouse
						%	%	67. Natatorium
						%	%	68. Wood Deck
						%	%	69. Jacuzzi

PHOTO

NOTES: BASEMENT - 1 CAR GARAGE W/ ENTRY POOR