


MAP 20 LOT 18-F ACCOUNT NO. 1799 BUILDING RECORD ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING	<u>0</u>	INSULATION		
1. Conv. 6. Split Lev.	<u>4</u>	FIN BSMT GRADE		1. Full 4. Minimal	<u>1</u>	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				UNFINISHED %		
5. Garrison				GRADE & FACTOR		
DWELLING UNITS	<u>1</u>	HEAT TYPE	<u>1</u>	1. E 4. B	<u>3</u>	
OTHER UNITS	<u>0</u>	1. HW BB 6. Grav. WA		2. D 5. A		
STORIES	<u>1</u>	2. HW CI 7. Electric		3. C 6. AA		
1. One 4. 1 1/2		3. HW Radiant 8. Units		SQ. FOOTAGE	<u>816</u>	
2. Two 5. 1 3/4		4. Steam 9. No Heat		CONDITION		
3. Three 6. 2 1/2		5. FWA	<u>9</u>	1. Poor 5. Avg +	<u>5</u>	
EXTERIOR WALLS		1. Central 9. None	<u>2</u>	2. Fair 6. Good		
1. Clapboard 6. BR./Stone	<u>1</u>	KITCHEN STYLE		3. Avg - 7. V Good		
2. WD.SH. 7. Novelty			2. Typical 4. Obsolete			4. Avg. 8. Exc.
3. Comp. 8. AL/Vinyl			BATH(S) STYLE	<u>2</u>	PHYS. % GOOD	
4. ASB/ASP 9. Other			1. Good 3. Old Style		FUNCT. % GOOD	
5. T1-11			2. Typical 4. Obsolete		FUNCT. CODE	
ROOF SURFACE		# ROOMS	<u>5</u>	1. Incomp. 5. CDU	<u>9</u>	
1. Asphalt 4. Comp.	<u>1</u>	# BEDROOMS	<u>3</u>	2. Overbuilt 6. Style		
2. Slate 5. Wood			3. Delap. 7. Layout			
3. Metal 6. Other			4. Small Size 8. Other			9. None
S/F MASONRY TRIM			# FULL BATHS	<u>1</u>	ECON. % GOOD	
YEAR BUILT		<u>1986</u>	# HALF BATHS		ECON. CODE	
YEAR REMODELED		# ADDN FIXTURES	<u>0</u>	1. Location 3. Services		
FOUNDATION		# FIREPLACES	<u>0</u>	2. Encroach 9. None		
1. Conc. 4. Wood	<u>1</u>	# HEARTHES	<u>0</u>	ENTRANCE CODE		
2. C Blk 5. Slab			LAYOUT		1. Inspct. 3. Vacant	
3. Br./Stone 6. Piers			1. Typical 2. In adeq.		2. Refused 5. Estim.	
BASEMENT			ATTIC		3. Info Only	
1. 1/4 3. 3/4 5. Crawl		<u>4</u>	1. 1/4 Fin 4. Full Fin.	<u>4</u>	INFO. CODE	
2. 1/2 4. Full 6. None		2. 1/2 Fin. 5. FI/Stairs		1. Owner 4. Agent	<u>5</u>	
BSMT GAR # CARS	<u>0</u>	3. 3/4 Fin. 9. None		2. Relative 5. Estimate		
WET BASEMENT	<u>1</u>	INT COMP TO EXIT + = -		3. Tenant 6. Other		
1. Dry 3. Wet		INSPECTED BY	<u>JLD</u>	2. Refused 5. Estim.		
2. Damp 9. None		DATE INSPECTED	<u>10/27/05</u>			



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWL	004	816	300	4	___%	___%	1. 1S Fr.	
DK	008	80		4	___%	___%	2. 2S Fr.	
					___%	___%	3. 3S Fr.	
					___%	___%	4. 1 1/2S Fr.	
					___%	___%	5. 1 3/4S Fr.	
					___%	___%	6. 2 1/2S Fr.	
					___%	___%	Add 10 for Bsmt	
					___%	___%	21. OFP	
					___%	___%	22. EFP	
					___%	___%	23. Garage	
					___%	___%	24. Shed	
					___%	___%	25. Bay Window	
					___%	___%	26. Overhang	
					___%	___%	27. Unf. Bsmt	
					___%	___%	28. Unf. Attic	
					___%	___%	29. Fin. Attic	
					___%	___%	Add 20 for 2 Story	
					___%	___%	61. Carport	
					___%	___%	62. Patio	
					___%	___%	63. Swimming Pool	
					___%	___%	64. Tennis Court	
					___%	___%	65. Stable w/loft	
					___%	___%	66. Greenhouse	
					___%	___%	67. Natatorium	
					___%	___%	68. Wood Deck	
					___%	___%	69. Jacuzzi	

PHOTO

NOTES: