




MAP 27 LOT 2 ACCOUNT NO. 1961 ADDRESS \_\_\_\_\_

CARD NO. \_\_\_\_ OF \_\_\_\_

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	=	<b>INSULATION</b>		
1. Conv. 6. Split Lev.	4	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other		<b>HEAT TYPE</b>		<b>UNFINISHED %</b>	%	
5. Garrison		1. HW BB 6. Grav. WA	1	<b>GRADE &amp; FACTOR</b>	98	
<b>DWELLING UNITS</b>	1	2. HW CI 7. Electric			1. E 4. B	3-
<b>OTHER UNITS</b>	1	3. HW Radiant 8. Units			2. D 5. A	
<b>STORIES</b>		4. Steam 9. No Heat			3. C 6. AA	
1. One 4. 1 1/2	1	5. FWA		%	<b>SQ. FOOTAGE</b>	672
2. Two 5. 1 3/4		<b>COOL TYPE</b>		<b>CONDITION</b>		
3. Three 6. 2 1/2		1. Central 9. None	9 %	1. Poor 5. Avg +	4	
<b>EXTERIOR WALLS</b>		<b>KITCHEN STYLE</b>		2. Fair 6. Good		
1. Clapboard 6. BR./Stone	2	1. Good 3. Old Style	2	3. Avg - 7. V Good		
2. WD.SH. 7. Novelty			2. Typical 4. Obsolete			4 Avg. 8. Exc.
3. Comp. 8. AL/Vinyl			<b>BATH(S) STYLE</b>	2	<b>PHYS. % GOOD</b>	%
4. ASB/ASP 9. Other			1. Good 3. Old Style		<b>FUNCT. % GOOD</b>	%
5. T1-11			2. Typical 4. Obsolete		<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		<b># ROOMS</b>	6	1. Incomp. 5. CDU	9	
1. Asphalt 4. Comp.	1	<b># BEDROOMS</b>	3	2. Overbuilt 6. Style		
2. Slate 5. Wood		<b># FULL BATHS</b>	1	3. Delap. 7. Layout		
3. Metal 6. Other		<b># HALF BATHS</b>	1	4. Small Size 8. Other		
<b>S/F MASONRY TRIM</b>		<b># ADDN FIXTURES</b>		9. None		
<b>YEAR BUILT</b>	1911	<b># FIREPLACES</b>		<b>ECON. % GOOD</b>	%	
<b>YEAR REMODELED</b>		<b># HEARTHES</b>		<b>ECON. CODE</b>		
<b>FOUNDATION</b>		<b>LAYOUT</b>	1	1. Location 3. Services		
1. Conc. 4. Wood	3	1. Typical 2. In adeq.		2. Encroach 9. None		
2. C Blk 5. Stab			<b>ATTIC</b>		<b>ENTRANCE CODE</b>	
3. Br./Stone 6. Piers			1. 1/4 Fin. 4. Full Fin.	4	1. Inspt. 3. Vacant	5
<b>BASEMENT</b>		2. 1/2 Fin. 5. Fl/Stairs			2. Refused 5. Estim.	
1. 1/4 3. 3/4 5. Crawl	4	3. 3/4 Fin. 9. None			3. Info Only	
2. 1/2 4. Full 6. None		<b>INT COMP TO EXIT + = -</b>		<b>INFO. CODE</b>		
<b>BSMT GAR # CARS</b>	0	<b>INSPECTED BY</b>	JLP	1. Owner 4. Agent	5	
<b>WET BASEMENT</b>		<b>DATE INSPECTED</b>	9/27/05	2. Relative 5. Estimate		
1. Dry 3. Wet	1			3. Tenant 6. Other		
2. Damp 9. None				2. Refused 5. Estim.		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
DWC	001	1911	672	3.00	4	___ %	___ %	1. 1S Fr.
ADD	001		408		4	___ %	___ %	2. 2S Fr.
OFF	021		168		4	___ %	___ %	3. 3S Fr.
GAR	060		600		4	___ %	___ %	4. 1 1/2S Fr.
SHD	024		32		4	___ %	___ %	5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								Add 10 for Bsmt
								21. OFF
								22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								Add 20 for 2 Story
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES: