




BUILDING RECORD

MAP LOT ACCOUNT NO. 2146 ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>		
1. Conv. 6. Split Lev.	1	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	1	
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 8. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>		125 %
5. Garrison				<b>GRADE &amp; FACTOR</b>		3
<b>DWELLING UNITS</b>	1	<b>HEAT TYPE</b>	1	1. E 4. B		
<b>OTHER UNITS</b>	0	1. HW BB 6. Grav. WA		2. D 5. A		
<b>STORIES</b>		2. HW Cl 7. Electric		3. C 6. AA		
1. One 4. 1 1/2	2	3. HW Radiant 8. Units		<b>SQ. FOOTAGE</b>	960	
2. Two 5. 1 3/4				<b>CONDITION</b>	6	
3. Three 6. 2 1/2				1. Poor 5. Avg +		
<b>EXTERIOR WALLS</b>		4. Steam 9. No Heat	9 %	2. Fair 6. Good		
1. Clapboard 6. BR./Stone	1	5. FWA		3. Avg - 7. V Good		
2. WD.SH. 7. Novelty			<b>COOL TYPE</b>		4. Avg. 8. Exc.	
3. Comp. 8. AL/Vinyl			1. Central 9. None		<b>PHYS. % GOOD</b>	
4. ASB/ASP 9. Other			<b>KITCHEN STYLE</b>	1	<b>FUNCT. % GOOD</b>	
5. T1-11			1. Good 3. Old Style		<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		2. Typical 4. Obsolete		1. Incomp. 5. CDU	9	
1. Asphalt 4. Comp.	3	<b>BATH(S) STYLE</b>	1	2. Overbuilt 6. Style		
2. Slate 5. Wood			1. Good 3. Old Style		3. Delap. 7. Layout	
3. Metal 6. Other			2. Typical 4. Obsolete		4. Small Size 8. Other	
<b>S/F MASONRY TRIM</b>		<b># ROOMS</b>	6	5. None 9. None		
1. Conc. 4. Wood	1983	<b># BEDROOMS</b>	3	<b>ECON. % GOOD</b>		
2. Slate 5. Wood			<b># FULL BATHS</b>	2	<b>ECON. CODE</b>	
3. Metal 6. Other			<b># HALF BATHS</b>	0	1. Location 3. Services	
<b>YEAR BUILT</b>		<b># ADDN FIXTURES</b>	0	2. Encroach 9. None		
<b>YEAR REMODELED</b>		<b># FIREPLACES</b>	0	<b>ENTRANCE CODE</b>	1	
<b>FOUNDATION</b>		<b># HEARTHES</b>	0	1. Inspct. 3. Vacant		
1. Conc. 4. Wood	1	<b>LAYOUT</b>		2. Refused 5. Estim.		
2. C Blk 5. Stab			1. Typical 2. In adeq.		3. Info Only	
3. Br./Stone 6. Piers			<b>ATTIC</b>	unfinishd	<b>INFO. CODE</b>	6
<b>BASEMENT</b>		1. 1/4 Fin. 4. Full Fin.	2	1. Owner 4. Agent		
1. 1/4 3. 3/4 5. Crawl	4	2. 1/2 Fin. 5. Fl/Stairs		2. Relative 5. Estimate		
2. 1/2 4. Full 6. None			3. 3/4 Fin. 9. None		3. Tenant 6. Other	
<b>BSMT GAR # CARS</b>			<b>INT COMP TO EXIT + = -</b>		2. Refused 5. Estim.	
<b>WET BASEMENT</b>		<b>INSPECTED BY</b>	211			
1. Dry 3. Wet	1	<b>DATE INSPECTED</b>	10/5/05			
2. Damp 9. None						



Brown

ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
Shed	24		200	200				1. 1S Fr.
Patio	62		1324	324				2. 2S Fr.
1st OTI	26		64					3. 3S Fr.
2nd	02	LINE	960					4. 1 1/2S Fr.
deck	68		90					5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								Add 10 for Bsmt
								21. OFP
								22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								Add 20 for 2 Story
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES:

GAR 43 1999 864 3.00 (on lot 57A) R