




BUILDING RECORD

MAP 42 LOT A288 ACCOUNT NO. 2658 ADDRESS \_\_\_\_\_

CARD NO. \_\_\_\_ OF \_\_\_\_

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>	<u>400</u>	<b>INSULATION</b>	<u>1</u>
1. Conv.	6. Split Lev.	<b>FIN BSMT GRADE</b>	<u>3</u>	1. Full	4. Minimal
2. Ranch	7. Contemp.			2. Heavy	9. None
3. R. Ranch	8. Log			3. Capped	
4. Cape	9. Other			<b>UNFINISHED %</b>	<u>115</u> %
5. Garrison				<b>GRADE &amp; FACTOR</b>	<u>3+</u>
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>	<u>1</u>	1. E	4. B
<b>OTHER UNITS</b>		1. HW BB		2. D	5. A
<b>STORIES</b>		2. HW CI		3. C	6. AA
1. One	4. 1 1/2	3. HW Radiant		<b>SQ. FOOTAGE</b>	<u>1012</u>
2. Two	5. 1 3/4	4. Steam		<b>CONDITION</b>	<u>5</u>
3. Three	6. 2 1/2	5. FWA	<u>%</u>	1. Poor	5. Avg +
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>	<u>9</u> %	2. Fair	6. Good
1. Clapboard	6. BR./Stone	1. Central		3. Avg -	7. V Good
2. WD.SH.	7. Novelty	9. None		4. Avg.	8. Exc.
3. Comp.	8. AL/Vinyl			<b>PHYS. % GOOD</b>	<u>%</u>
4. ASB/ASP	9. Other	<b>KITCHEN STYLE</b>	<u>2</u>	<b>FUNCT. % GOOD</b>	<u>%</u>
5. T1-11		1. Good		<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>		2. Typical		1. Incomp.	5. CDU
1. Asphalt	4. Comp.	<b>BATH(S) STYLE</b>	<u>2</u>	2. Overbuilt	6. Style
2. Slate	5. Wood	1. Good		3. Delap.	7. Layout
3. Metal	6. Other	2. Typical		4. Small Size	8. Other
<b>S/F MASONRY TRIM</b>		3. Old Style		9. None	
<b>YEAR BUILT</b>		4. Obsolete		<b>ECON. % GOOD</b>	<u>%</u>
<b>YEAR REMODELED</b>		<b># ROOMS</b>	<u>3</u>	<b>ECON. CODE</b>	<u>9</u>
<b>FOUNDATION</b>		<b># BEDROOMS</b>	<u>3</u>	1. Location	3. Services
1. Conc.	4. Wood	<b># FULL BATHS</b>	<u>1</u>	2. Encroach	9. None
2. C Blk	5. Slab	<b># HALF BATHS</b>	<u>9</u>	<b>ENTRANCE CODE</b>	<u>5</u>
3. Br./Stone	6. Piers	<b># ADDN FIXTURES</b>		1. Inspct.	3. Vacant
<b>BASEMENT</b>		<b># FIREPLACES</b>		2. Refused	5. Estim.
1. 1/4	3. 3/4	<b># HEARTHES</b>		3. Info Only	
2. 1/2	4. Full	<b>LAYOUT</b>	<u>1</u>	<b>INFO. CODE</b>	<u>5</u>
5. Crawl	6. None	1. Typical		1. Owner	4. Agent
<b>BSMT GAR # CARS</b>		2. In adeq.		2. Relative	5. Estimate
<b>WET BASEMENT</b>		<b>ATTIC</b>	<u>9</u>	3. Tenant	6. Other
1. Dry	3. Wet	1. 1/4 Fin		2. Refused	5. Estim.
2. Damp	9. None	2. 1/2 Fin.			
		5. Fl/Stairs			
		9. None			
		<b>INT COMP TO EXIT + = -</b>			
		<b>INSPECTED BY</b>	<u>MR</u>		
		<b>DATE INSPECTED</b>	<u>7-22-05</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
					Phys.	Funct.	
<u>15</u>	<u>1989</u>	<u>1012</u>	---	---	---	---	1. 1S Fr.
<u>OH</u>	---	<u>0037</u>	---	---	---	---	2. 2S Fr.
<u>DK</u>	---	<u>0128</u>	---	---	---	---	3. 3S Fr.
---	---	---	---	---	---	---	4. 1 1/2S Fr.
---	---	---	---	---	---	---	5. 1 3/4S Fr.
---	---	---	---	---	---	---	6. 2 1/2S Fr.
---	---	---	---	---	---	---	<b>Add 10 for Bemt</b>
---	---	---	---	---	---	---	21. OFF
---	---	---	---	---	---	---	22. EFP
---	---	---	---	---	---	---	23. Garage
---	---	---	---	---	---	---	24. Shed
---	---	---	---	---	---	---	25. Bay Window
---	---	---	---	---	---	---	26. Overhang
---	---	---	---	---	---	---	27. Unf. Bsmt
---	---	---	---	---	---	---	28. Unf. Attic
---	---	---	---	---	---	---	29. Fin. Attic
---	---	---	---	---	---	---	<b>Add 20 for 2 Story</b>
---	---	---	---	---	---	---	61. Carport
---	---	---	---	---	---	---	62. Patio
---	---	---	---	---	---	---	63. Swimming Pool
---	---	---	---	---	---	---	64. Tennis Court
---	---	---	---	---	---	---	65. Stable w/toft
---	---	---	---	---	---	---	66. Greenhouse
---	---	---	---	---	---	---	67. Natatorium
---	---	---	---	---	---	---	68. Wood Deck
---	---	---	---	---	---	---	69. Jacuzzi

PHOTO

NOTES: