




MAP **42** LOT **A159** ACCOUNT NO. **2552** BUILDING RECORD ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>	
1. Conv.	6. Spill Lev.	-		1. Full	4. Minimal
2. Ranch	7. Contemp.			2. Heavy	9. None
3. R. Ranch	8. Log			3. Capped	
4. Cape	9. Other			<b>UNFINISHED %</b>	
5. Garrison				<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>		1. E	4. B
<b>OTHER UNITS</b>		1. HW BB	6. Grav. WA	2. D	5. A
<b>STORIES</b>		2. HW CI	7. Electric	3. C	6. AA
1. One	4. 1 1/2	3. HW Radiant	8. Units	<b>SQ. FOOTAGE</b>	
2. Two	5. 1 3/4	4. Steam	9. No Heat	768	
3. Three	6. 2 1/2	5. FWA		<b>CONDITION</b>	
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>		1. Poor	5. Avg +
1. Clapboard	8. BR./Stone	1. Central	9. None	2. Fair	6. Good
2. WD.SH.	7. Novelty			3. Avg -	7. V Good
3. Comp.	8. AL/Vinyl			4. Avg.	8. Exc.
4. ASB/ASP	9. Other			<b>PHYS. % GOOD</b>	
5. T1-11				<b>FUNCT. % GOOD</b>	
<b>ROOF SURFACE</b>		<b>KITCHEN STYLE</b>		<b>FUNCT. CODE</b>	
1. Asphalt	4. Comp.	1. Good	3. Old Style	1. Incomp.	5. CDU
2. Slate	5. Wood	2. Typical	4. Obsolete	2. Overbuilt	6. Style
3. Metal	8. Other			3. Delap.	7. Layout
<b>S/F MASONRY TRIM</b>		<b>BATH(S) STYLE</b>		4. Small Size	8. Other
<b>YEAR BUILT</b>		1. Good	3. Old Style	9. None	
1993		2. Typical	4. Obsolete	<b>ECON. % GOOD</b>	
<b>YEAR REMODELED</b>		<b># ROOMS</b>		<b>ECON. CODE</b>	
		3		1. Location	3. Services
<b>FOUNDATION</b>		<b># BEDROOMS</b>		2. Encroach	9. None
1. Conc.	4. Wood	7		<b>ENTRANCE CODE</b>	
2. C Blk	5. Slab	<b># FULL BATHS</b>		1. Inspct.	3. Vacant
3. Br./Stone	6. Piers	1		2. Refused	5. Estim.
<b>BASEMENT</b>		<b># HALF BATHS</b>		3. Info Only	
1. 1/4	3. 3/4	1		<b>INFO. CODE</b>	
2. 1/2	4. Full	<b># ADDN FIXTURES</b>		1. Owner	4. Agent
	5. Crawl	2		2. Relative	5. Estimate
	6. None	<b># FIREPLACES</b>		3. Tenant	6. Other
<b>BSMT GAR # CARS</b>		<b># HEARTHES</b>		2. Refused	5. Estim.
0		1		<b>CODES</b>	
<b>WET BASEMENT</b>		<b>LAYOUT</b>		1. 1S Fr.	
1. Dry	3. Wet	1. Typical	2. In adeq.	2. 2S Fr.	
2. Damp	9. None	<b>ATTIC</b>		3. 3S Fr.	
		1. 1/4 Fin	4. Full Fin.	4. 1 1/2S Fr.	
		2. 1/2 Fin.	5. F/Stairs	5. 1 3/4S Fr.	
		3. 3/4 Fin.	9. None	6. 2 1/2S Fr.	
		<b>INT COMP TO EXIT + - -</b>		<b>Add 10 for Bsmt</b>	
		INSPECTED BY		21. OFF	
		RAK		22. EFP	
		DATE INSPECTED		23. Garage	
		7-105		24. Shed	
				25. Bay Window	
				26. Overhang	
				27. Unf. Bsmt	
				28. Unf. Attic	
				29. Fin. Attic	
				<b>Add 20 for 2 Story</b>	
				61. Carport	
				62. Patio	
				63. Swimming Pool	
				64. Tennis Court	
				65. Stable w/loft	
				66. Greenhouse	
				67. Natatorium	
				68. Wood Deck	
				69. Jacuzzi	



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
1 1/2	004	1993	0768					1. 1S Fr.
DK	068		0064					2. 2S Fr.
EFP	022		0025					3. 3S Fr.
								4. 1 1/2S Fr.
								5. 1 3/4S Fr.
								6. 2 1/2S Fr.
								<b>Add 10 for Bsmt</b>
								21. OFF
								22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								<b>Add 20 for 2 Story</b>
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES: