


4R

BUILDING RECORD

MAP 45 LOT 1465 ACCOUNT NO. 3296 ADDRESS _____

CARD NO. _____ OF _____

BUILDING STYLE 1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison	<u>2</u>	S/F BSMT LIVING FIN BSMT GRADE		INSULATION 1. Full 4. Minimal 2. Heavy 9. None 3. Capped	<u>1</u>
DWELLING UNITS OTHER UNITS	<u>1</u>	HEAT TYPE 1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA	<u>100</u> %	UNFINISHED % GRADE & FACTOR 1. E 4. B 2. D 5. A 3. C 6. AA	<u>3+</u>
STORIES 1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 8. 2 1/2	<u>1</u>	COOL TYPE 1. Central 9. None	<u>9</u> %	SQ. FOOTAGE CONDITION 1. Poor 5. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	<u>7</u>
EXTERIOR WALLS 1. Clapboard 6. BR/Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Mvnyl 4. ASB/ASP 9. Other 5. T1-11	<u>8</u>	KITCHEN STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	PHYS. % GOOD FUNCT. % GOOD FUNCT. CODE 1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	<u>100</u> % <u>100</u> %
ROOF SURFACE 1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other	<u>1</u>	BATH(S) STYLE 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	ECON. % GOOD ECON. CODE 1. Location 3. Services 2. Encroach 9. None	<u>100</u> %
S/F MASONRY TRIM		# ROOMS # BEDROOMS # FULL BATHS # HALF BATHS # ADDN FIXTURES	<u>5</u> <u>3</u> <u>1</u>	ENTRANCE CODE 1. Inspec. 3. Vacant 2. Refused 5. Estim. 3. Info Only	<u>9</u>
YEAR BUILT YEAR REMODELED	<u>2003</u>	# FIREPLACES # HEARTHES	<u>1</u>	INFO. CODE 1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim.	<u>5</u>
FOUNDATION 1. Conc. 4. Wood 2. C Blk 5. Slab 3. Br./Stone 6. Piers	<u>1</u>	LAYOUT 1. Typical 2. In adeq.	<u>1</u>		<u>5</u>
BASEMENT 1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None	<u>4</u>	ATTIC 1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. FV/Stairs 3. 3/4 Fin. 9. None	<u>9</u>		<u>5</u>
BSMT GAR # CARS WET BASEMENT 1. Dry 3. Wet 2. Damp 9. None	<u>1</u>	INT COMP TO EXIT + = - INSPECTED BY DATE INSPECTED	<u>KSH</u> <u>8/10/05</u>		<u>5</u>



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
<u>15/18</u>	<u>1</u>	<u>768</u>			___ %	___ %	1. 1S Fr.	
<u>WD</u>	<u>68</u>	<u>144</u>			___ %	___ %	2. 2S Fr.	
					___ %	___ %	3. 3S Fr.	
					___ %	___ %	4. 1 1/2S Fr.	
					___ %	___ %	5. 1 3/4S Fr.	
					___ %	___ %	6. 2 1/2S Fr.	
					___ %	___ %	Add 10 for Bsmt	
					___ %	___ %	21. OFP	
					___ %	___ %	22. EFP	
					___ %	___ %	23. Garage	
					___ %	___ %	24. Shed	
					___ %	___ %	25. Bay Window	
					___ %	___ %	26. Overhang	
					___ %	___ %	27. Unf. Bsmt	
					___ %	___ %	28. Unf. Attic	
					___ %	___ %	29. Fin. Attic	
					___ %	___ %	Add 20 for 2 Story	
					___ %	___ %	61. Carport	
					___ %	___ %	62. Patio	
					___ %	___ %	63. Swimming Pool	
					___ %	___ %	64. Tennis Court	
					___ %	___ %	65. Stable w/loft	
					___ %	___ %	66. Greenhouse	
					___ %	___ %	67. Natatorium	
					___ %	___ %	68. Wood Deck	
					___ %	___ %	69. Jacuzzi	

PHOTO

NOTES: