




180

MAP 45 LOT 1648 ACCOUNT NO. 3440 ADDRESS \_\_\_\_\_

CARD NO. \_\_\_\_ OF \_\_\_\_

<b>BUILDING STYLE</b>		2	<b>S/F BSMT LIVING</b>		1	<b>INSULATION</b>		1
1. Conv.	6. Split Lev.		<b>FIN BSMT GRADE</b>			1. Full	4. Minimal	
2. Ranch	7. Contemp.	1	<b>HEAT TYPE</b>		100 %	2. Heavy	9. None	3+
3. R. Ranch	8. Log		1. HW BB			6. Grav. WA	<b>UNFINISHED %</b>	
4. Cape	9. Other	1	2. HW CI		9 %	<b>GRADE &amp; FACTOR</b>		6
5. Garrison			3. HW Radiant			7. Electric	1. E	
<b>DWELLING UNITS</b>		5	4. Steam		2	2. D	5. A	100 %
<b>OTHER UNITS</b>			5. FWA			8. Units	3. C	
<b>STORIES</b>		1	<b>COOL TYPE</b>		2	<b>SQ. FOOTAGE</b>		100 %
1. One	4. 1 1/2		1. Central			9. None	<b>CONDITION</b>	
2. Two	5. 1 3/4	5	<b>KITCHEN STYLE</b>		2	1. Poor	5. Avg +	100 %
3. Three	6. 2 1/2		1. Good			3. Old Style	2. Fair	
<b>EXTERIOR WALLS</b>		1	2. Typical		2	3. Avg -	7. V Good	100 %
1. Clapboard	6. BR./Stone		3. Old Style			4. Obsolete	4. Avg.	
2. WD.SH.	7. Novelty	1	<b>BATH(S) STYLE</b>		6	<b>PHYS. % GOOD</b>		100 %
3. Comp.	8. AL/Minyl		2. Typical			4. Obsolete	<b>FUNCT. % GOOD</b>	
4. ASB/ASP	9. Other	1	<b># ROOMS</b>		9	<b>FUNCT. CODE</b>		9
5. T1-11			<b># BEDROOMS</b>			1. Incomp.	5. CDU	
<b>ROOF SURFACE</b>		1	<b># FULL BATHS</b>		9	2. Overbuilt	6. Style	100 %
1. Asphalt	4. Comp.		<b># HALF BATHS</b>			3. Delap.	7. Layout	
2. Slate	5. Wood	1	<b># ADDN FIXTURES</b>		9	4. Small Size	8. Other	100 %
3. Metal	6. Other		<b># FIREPLACES</b>			9. None	<b>ECON. % GOOD</b>	
<b>S/F MASONRY TRIM</b>		1	<b># HEARTHES</b>		9	<b>ECON. CODE</b>		1
<b>YEAR BUILT</b>			1972			1. Typical	2. In adeq.	
<b>YEAR REMODELED</b>		4	1985		9	2. Encroach	9. None	5
<b>FOUNDATION</b>			1			<b>ATTIC</b>		
1. Conc.	4. Wood	1	1. 1/4 Fin		9	1. Inspect.	3. Vacant	5
2. C Blk	5. Stab		2. 1/2 Fin			5. F/Stairs	2. Refused	
3. Br./Stone	6. Piers	4	3. 3/4 Fin		9	3. Info Only	<b>INFO. CODE</b>	
<b>BASEMENT</b>			INT COMP TO EXIT + = -			<b>INSPECTED BY</b>		1. Owner
1. 1/4	3. 3/4	1	KSH		5	2. Relative	5. Estimate	5
2. 1/2	4. Full		8/16/05			3. Tenant	6. Other	
<b>BSMT GAR # CARS</b>		1	<b>DATE INSPECTED</b>		2. Refused		5. Estim.	5
<b>WET BASEMENT</b>			1		<b>CODES</b>			



**ADDITIONS, OUTBUILDINGS & IMPROVEMENTS**

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		
						Phys.	Funct.	
15/B	1		1904			%	%	1. 1S Fr.
GAR	23		720			%	%	2. 2S Fr.
352sqP	72		130			%	%	3. 3S Fr.
EP	22		336			%	%	4. 1 1/2S Fr.
						%	%	5. 1 3/4S Fr.
						%	%	6. 2 1/2S Fr.
						%	%	Add 10 for Bsmt
						%	%	21. OFP
						%	%	22. EFP
						%	%	23. Garage
						%	%	24. Shed
						%	%	25. Bay Window
						%	%	26. Overhang
						%	%	27. Unf. Bsmt
						%	%	28. Unf. Attic
						%	%	29. Fin. Attic
						%	%	Add 20 for 2 Story
						%	%	61. Carport
						%	%	62. Patio
						%	%	63. Swimming Pool
						%	%	64. Tennis Court
						%	%	65. Stable w/loft
						%	%	66. Greenhouse
						%	%	67. Natatorium
						%	%	68. Wood Deck
						%	%	69. Jacuzzi

PHOTO

NOTES: