




13X

BUILDING RECORD

MAP LOT ACCOUNT NO. ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>	
1. Conv.	6. Split Lev.	<b>FIN BSMT GRADE</b>		1. Full	4. Minimal
2. Ranch	7. Contemp.			2. Heavy	9. None
3. R. Ranch	8. Log			3. Capped	
4. Cape	9. Other			<b>UNFINISHED %</b>	
5. Garrison				<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>		1. E	4. B
		1. HW BB	6. Grav. WA	2. D	5. A
		2. HW CI	7. Electric	3. C	6. AA
<b>OTHER UNITS</b>		3. HW Radiant	8. Units	<b>SQ. FOOTAGE</b>	
		4. Steam	9. No Heat		
<b>STORIES</b>		5. FWA		<b>CONDITION</b>	
1. One	4. 1 1/2	<b>COOL TYPE</b>		1. Poor	5. Avg +
2. Two	5. 1 3/4	1. Central	9. None	2. Fair	6. Good
3. Three	6. 2 1/2			3. Avg -	7. V Good
<b>EXTERIOR WALLS</b>				4. Avg.	8. Exc.
1. Clapboard	6. BR./Stone	<b>KITCHEN STYLE</b>		<b>PHYS. % GOOD</b>	
2. WD.SH.	7. Novelty	1. Good	3. Old Style	<b>FUNCT. % GOOD</b>	
3. Comp.	8. AL/Vinyl	2. Typical	4. Obsolete	<b>FUNCT. CODE</b>	
4. ASB/ASP	9. Other			1. Incomp.	5. CDU
5. T1-11		<b>BATH(S) STYLE</b>		2. Overbuilt	6. Style
<b>ROOF SURFACE</b>		1. Good	3. Old Style	3. Delap.	7. Layout
1. Asphalt	4. Comp.	2. Typical	4. Obsolete	4. Small Size	8. Other
2. Slate	5. Wood			9. None	
3. Metal	6. Other	<b># ROOMS</b>		<b>ECON. % GOOD</b>	
<b>S/F MASONRY TRIM</b>		3		<b>ECON. CODE</b>	
<b>YEAR BUILT</b>		<b># BEDROOMS</b>		1. Location	3. Services
1986		3		2. Encroach	9. None
<b>YEAR REMODELED</b>		<b># FULL BATHS</b>		<b>ENTRANCE CODE</b>	
		1		1. Inspct.	3. Vacant
<b>FOUNDATION</b>		<b># HALF BATHS</b>		2. Refused	5. Estim.
1. Conc.	4. Wood	0		3. Info Only	
2. C Blk	5. Slab	<b># ADDN FIXTURES</b>		<b>INFO. CODE</b>	
3. Br./Stone	6. Piers	0		1. Owner	4. Agent
<b>BASEMENT</b>		<b># FIREPLACES</b>		2. Relative	5. Estimate
1. 1/4	3. 3/4	0		3. Tenant	6. Other
2. 1/2	4. Full	<b># HEARTHES</b>		2. Refused	5. Estim.
5. Crawl	6. None	0			
<b>BSMT GAR # CARS</b>		<b>LAYOUT</b>			
0		1. Typical	2. In adeq.		
<b>WET BASEMENT</b>		<b>ATTIC</b>			
1. Dry	3. Wet	1. 1/4 Fin	4. Full Fin.		
2. Damp	9. None	2. 1/2 Fin.	5. Fl/Stairs		
		3. 3/4 Fin.	9. None		
		<b>INT COMP TO EXIT + = -</b>			
		0			
		<b>INSPECTED BY</b>			
		KSH			
		<b>DATE INSPECTED</b>			
		7/21/05			



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
15/B		768			%	%	1. 1S Fr.	
15		240			%	%	2. 2S Fr.	
WD	68	336			%	%	3. 3S Fr.	
WD	68	60			%	%	4. 1 1/2S Fr.	
					%	%	5. 1 3/4S Fr.	
					%	%	6. 2 1/2S Fr.	
					%	%	Add 10 for Bsmt	
					%	%	21. OFP	
					%	%	22. EFP	
					%	%	23. Garage	
					%	%	24. Shed	
					%	%	25. Bay Window	
					%	%	26. Overhang	
					%	%	27. Unf. Bsmt	
					%	%	28. Unf. Attic	
					%	%	29. Fin. Attic	
					%	%	Add 20 for 2 Story	
					%	%	61. Carport	
					%	%	62. Patio	
					%	%	63. Swimming Pool	
					%	%	64. Tennis Court	
					%	%	65. Stable w/loft	
					%	%	66. Greenhouse	
					%	%	67. Natatorium	
					%	%	68. Wood Deck	
					%	%	69. Jacuzzi	

PHOTO

NOTES: