




BUILDING RECORD

MAP 47 LOT 27 ACCOUNT NO. 3867 ADDRESS \_\_\_\_\_ CARD NO. \_\_\_\_ OF \_\_\_\_

<b>BUILDING STYLE</b> 1. Conv. 6. Split Lev. 2. Ranch 7. Contemp. 3. R. Ranch 8. Log 4. Cape 9. Other 5. Garrison	<u>2</u>	<b>S/F BSMT LIVING</b> FIN BSMT GRADE	<u>100</u>	<b>INSULATION</b> 1. Full 4. Minimal 2. Heavy 9. None 3. Capped	<u>1</u>
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b> 1. HW BB 6. Grav. WA 2. HW CI 7. Electric 3. HW Radiant 8. Units 4. Steam 9. No Heat 5. FWA	<u>1</u>	<b>UNFINISHED %</b>	<u>   </u> %
<b>OTHER UNITS</b>		<b>COOL TYPE</b> 1. Central 9. None	<u>9</u>	<b>GRADE &amp; FACTOR</b> 1. E 4. B 2. D 5. A 3. C 6. AA	<u>3</u>
<b>STORIES</b> 1. One 4. 1 1/2 2. Two 5. 1 3/4 3. Three 6. 2 1/2	<u>1</u>	<b>KITCHEN STYLE</b> 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	<b>SQ. FOOTAGE</b>	<u>576</u>
<b>EXTERIOR WALLS</b> 1. Clapboard 6. BR./Stone 2. WD.SH. 7. Novelty 3. Comp. 8. AL/Vinyl 4. ASB/ASP 9. Other 5. T1-11	<u>7</u>	<b>BATH(S) STYLE</b> 1. Good 3. Old Style 2. Typical 4. Obsolete	<u>2</u>	<b>CONDITION</b> 1. Poor 6. Avg + 2. Fair 6. Good 3. Avg - 7. V Good 4. Avg. 8. Exc.	<u>4</u>
<b>ROOF SURFACE</b> 1. Asphalt 4. Comp. 2. Slate 5. Wood 3. Metal 6. Other	<u>1</u>	<b># ROOMS</b>	<u>9</u>	<b>PHYS. % GOOD</b>	<u>   </u> %
<b>S/F MASONRY TRIM</b>	<u>178</u>	<b># BEDROOMS</b>	<u>4</u>	<b>FUNCT. % GOOD</b>	<u>   </u> %
<b>YEAR BUILT</b>	<u>1978</u>	<b># FULL BATHS</b>	<u>1</u>	<b>FUNCT. CODE</b> 1. Incomp. 5. CDU 2. Overbuilt 6. Style 3. Delap. 7. Layout 4. Small Size 8. Other 9. None	<u>9</u>
<b>YEAR REMODELED</b>		<b># HALF BATHS</b>	<u>1</u>	<b>ECON. % GOOD</b>	<u>   </u> %
<b>FOUNDATION</b> 1. Conc. 4. Wood 2. C Blk 5. Stab 3. Br./Stone 6. Piers	<u>2</u>	<b># ADDN FIXTURES</b>	<u>9</u>	<b>ECON. CODE</b> 1. Location 3. Services 2. Encroach 9. None	<u>9</u>
<b>BASEMENT</b> 1. 1/4 3. 3/4 5. Crawl 2. 1/2 4. Full 6. None	<u>4</u>	<b># FIREPLACES</b>	<u>1</u>	<b>ENTRANCE CODE</b> 1. Inspcl, 3. Vacant 2. Refused 5. Estim. 3. Info Only	<u>2</u>
<b>BSMT GAR # CARS</b>	<u>0</u>	<b># HEARTHES</b>	<u>1</u>	<b>INFO. CODE</b> 1. Owner 4. Agent 2. Relative 5. Estimate 3. Tenant 6. Other 2. Refused 5. Estim.	<u>2</u>
<b>WET BASEMENT</b> 1. Dry 3. Wet 2. Damp 9. None	<u>1</u>	<b>LAYOUT</b> 1. Typical 2. In adeq.	<u>1</u>		
		<b>ATTIC</b> 1. 1/4 Fin 4. Full Fin. 2. 1/2 Fin. 5. F/Stairs 3. 3/4 Fin. 9. None	<u>9</u>		
		<b>INT COMP TO EXIT + - =</b>			
		<b>INSPECTED BY</b>	<u>PAK</u>		
		<b>DATE INSPECTED</b>	<u>1-27-06</u>		



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD		CODES
						Phys.	Funct.	
<u>12</u>	<u>1</u>	<u>1978</u>	<u>576</u>			<u>   </u> %	<u>   </u> %	1. 1S Fr.
<u>OH</u>	<u>26</u>		<u>48</u>			<u>   </u> %	<u>   </u> %	2. 2S Fr.
<u>DK</u>	<u>68</u>		<u>288</u>			<u>   </u> %	<u>   </u> %	3. 3S Fr.
<u>EP</u>	<u>22</u>		<u>288</u>			<u>   </u> %	<u>   </u> %	4. 1 1/2S Fr.
						<u>   </u> %	<u>   </u> %	5. 1 3/4S Fr.
						<u>   </u> %	<u>   </u> %	6. 2 1/2S Fr.
						<u>   </u> %	<u>   </u> %	Add 10 for Bsm
						<u>   </u> %	<u>   </u> %	21. OFF
						<u>   </u> %	<u>   </u> %	22. EFP
						<u>   </u> %	<u>   </u> %	23. Garage
						<u>   </u> %	<u>   </u> %	24. Shed
						<u>   </u> %	<u>   </u> %	25. Bay Window
						<u>   </u> %	<u>   </u> %	26. Overhang
						<u>   </u> %	<u>   </u> %	27. Unf. Bsm
						<u>   </u> %	<u>   </u> %	28. Unf. Attic
						<u>   </u> %	<u>   </u> %	29. Fin. Attic
						<u>   </u> %	<u>   </u> %	Add 20 for 2-Story
<u>0 shed</u>	<u>24</u>		<u>96</u>	<u>4</u>	<u>4</u>	<u>   </u> %	<u>   </u> %	61. Carport
<u>0 shed</u>	<u>24</u>		<u>192</u>	<u>4</u>	<u>4</u>	<u>   </u> %	<u>   </u> %	62. Patio
						<u>   </u> %	<u>   </u> %	63. Swimming Pool
						<u>   </u> %	<u>   </u> %	64. Tennis Court
						<u>   </u> %	<u>   </u> %	65. Stable w/loft
						<u>   </u> %	<u>   </u> %	66. Greenhouse
						<u>   </u> %	<u>   </u> %	67. Natatorium
						<u>   </u> %	<u>   </u> %	68. Wood Deck
						<u>   </u> %	<u>   </u> %	69. Jacuzzi

PHOTO

NOTES: