


BUILDING RECORD

MAP 49 LOT 10J ACCOUNT NO. 3984 ADDRESS _____

CARD NO. _____ OF _____

| | | | | | |
|-------------------------|---------------|-------------------------------|--------------|---------------------------|-------------|
| BUILDING STYLE | | S/F BSMT LIVING | | INSULATION | |
| 1. Conv. | 6. Split Lev. | <u>0</u> | | 1. Full | 4. Minimal |
| 2. Ranch | 7. Contemp. | | | 2. Heavy | 9. None |
| 3. R. Ranch | 8. Log | | | 3. Capped | |
| 4. Cape | 9. Other | | | UNFINISHED % | |
| 5. Garrison | | | | GRADE & FACTOR | |
| DWELLING UNITS | | HEAT TYPE | | 1. E | |
| | | 1. HW BB | 6. Grav. WA | 4. B | |
| | | 2. HW CI | 7. Electric | 2. D | 5. A |
| | | 3. HW Radiant | 8. Units | 3. C | 6. AA |
| | | 4. Steam | 9. No Heat | SQ. FOOTAGE | |
| | | 5. FWA | | CONDITION | |
| OTHER UNITS | | COOL TYPE | | 1. Poor | 5. Avg + |
| | | 1. Central | 9. None | 2. Fair | 6. Good |
| STORIES | | | | 3. Avg - | 7. V Good |
| 1. One | 4. 1 1/2 | | | 4. Avg. | 8. Exc. |
| 2. Two | 5. 1 3/4 | | | PHYS. % GOOD | |
| 3. Three | 6. 2 1/2 | | | FUNCT. % GOOD | |
| EXTERIOR WALLS | | KITCHEN STYLE | | FUNCT. CODE | |
| 1. Clapboard | 6. BR/Stone | 1. Good | 3. Old Style | 1. Incomp. | 5. CDU |
| 2. WD.SH. | 7. Novelty | 2. Typical | 4. Obsolete | 2. Overbuilt | 6. Style |
| 3. Comp. | 8. AL/Vinyl | | | 3. Delap. | 7. Layout |
| 4. ASB/ASP | 9. Other | | | 4. Small Size | 8. Other |
| 5. T1-11 | | | | 9. None | |
| ROOF SURFACE | | BATH(S) STYLE | | ECON. % GOOD | |
| 1. Asphalt | 4. Comp. | 1. Good | 3. Old Style | ECON. CODE | |
| 2. Slate | 5. Wood | 2. Typical | 4. Obsolete | 1. Location | 3. Services |
| 3. Metal | 6. Other | | | 2. Encroach | 9. None |
| S/F MASONRY TRIM | | # ROOMS | | ENTRANCE CODE | |
| YEAR BUILT | | # BEDROOMS | | 1. Inspct. | 3. Vacant |
| <u>1979</u> | | <u>3</u> | | 2. Refused | 5. Estim. |
| YEAR REMODELED | | # FULL BATHS | | 3. Info Only | |
| | | <u>1</u> | | INFO. CODE | |
| FOUNDATION | | # HALF BATHS | | 1. Owner | 4. Agent |
| 1. Conc. | 4. Wood | <u>0</u> | | 2. Relative | 5. Estimate |
| 2. C Blk | 5. Slab | # ADDN FIXTURES | | 3. Tenant | 6. Other |
| 3. Br/Stone | 6. Piers | <u>0</u> | | 2. Refused | 5. Estim. |
| BASEMENT | | # FIREPLACES | | | |
| 1. 1/4 | 3. 3/4 | <u>1</u> | | | |
| 2. 1/2 | 4. Full | # HEARTHES | | | |
| 5. Crawl | 6. None | <u>1</u> | | | |
| BSMT GAR # CARS | | LAYOUT | | | |
| <u>0</u> | | 1. Typical | 2. In adeq. | | |
| WET BASEMENT | | ATTIC | | | |
| 1. Dry | 3. Wet | 1. 1/4 Fin | | | |
| 2. Damp | 9. None | 2. 1/2 Fin. | | | |
| | | 3. 3/4 Fin. | | | |
| | | 4. Full Fin. | | | |
| | | 5. FI/Stairs | | | |
| | | 9. None | | | |
| | | INT COMP TO EXIT + = - | | | |
| | | <u>0</u> | | | |
| | | INSPECTED BY | | | |
| | | <u>BAK</u> | | | |
| | | DATE INSPECTED | | | |
| | | <u>11-21-05</u> | | | |



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

| TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD | | CODES |
|-------|------|-------|-------|------|--------------|--------|--------------------|
| | | | | | Phys. | Funct. | |
| 1 1/2 | 1979 | 864 | | | % | % | 1. 1S Fr. |
| 1 1/2 | | 144 | | | % | % | 2. 2S Fr. |
| A/GAR | 77 | 672 | | | % | % | 3. 3S Fr. |
| DK | 68 | 448 | | | % | % | 4. 1 1/2S Fr. |
| OP | 21 | 40 | | | % | % | 5. 1 3/4S Fr. |
| DK | 68 | 256 | | | % | % | 6. 2 1/2S Fr. |
| | | | | | % | % | Add 10 for Bsmt |
| | | | | | % | % | 21. OFP |
| | | | | | % | % | 22. EFP |
| | | | | | % | % | 23. Garage |
| | | | | | % | % | 24. Shed |
| | | | | | % | % | 25. Bay Window |
| | | | | | % | % | 26. Overhang |
| | | | | | % | % | 27. Unf. Bsmt |
| | | | | | % | % | 28. Unf. Attic |
| | | | | | % | % | 29. Fin. Attic |
| | | | | | % | % | Add 20 for 2 Story |
| | | | | | % | % | 61. Carport |
| | | | | | % | % | 62. Patio |
| | | | | | % | % | 63. Swimming Pool |
| | | | | | % | % | 64. Tennis Court |
| | | | | | % | % | 65. Stable w/loft |
| | | | | | % | % | 66. Greenhouse |
| | | | | | % | % | 67. Natatorium |
| | | | | | % | % | 68. Wood Deck |
| | | | | | % | % | 69. Jacuzzi |

PHOTO

NOTES:

① shed