


Handwritten notes: *Hot tub*, *PK*, *(110)*, *(3)*, *(4)*, *(1)*

MAP 51 LOT 5 ACCOUNT NO. _____ ADDRESS _____ CARD NO. _____ OF _____

BUILDING STYLE		S/F BSMT LIVING	<u>750</u>	INSULATION	
1. Conv. 6. Split Lev.	<u>2</u>	FIN BSMT GRADE	<u>3</u>	1. Full 4. Minimal	<u>1</u>
2. Ranch 7. Contemp.			<u>710</u>	2. Heavy 9. None	
3. R. Ranch 8. Log				3. Capped	
4. Cape 9. Other		HEAT TYPE	<u>1</u>	UNFINISHED %	<u>110</u> %
5. Garrison		1. HW BB 6. Grav. WA		GRADE & FACTOR	<u>3</u>
DWELLING UNITS		2. HW CI 7. Electric		1. E 4. B	
OTHER UNITS		3. HW Radiant 8. Units		2. D 5. A	
STORIES	<u>1</u>	4. Steam 9. No Heat		3. C 6. AA	
1. One 4. 1 1/2		5. FWA	<u>9</u> %	SQ. FOOTAGE	<u>100%</u>
2. Two 5. 1 3/4		COOL TYPE		CONDITION	<u>4</u>
3. Three 6. 2 1/2		1. Central 9. None	<u>2</u>	1. Poor 5. Avg +	
EXTERIOR WALLS	<u>1</u>	KITCHEN STYLE		2. Fair 6. Good	
1. Clapboard 6. BR./Stone		1. Good 3. Old Style	<u>2</u>	3. Avg - 7. V Good	
2. WD.SH. 7. Novelty		2. Typical 4. Obsolete		4. Avg. 8. Exc.	<u>9</u> %
3. Comp. 8. AL/Vinyl		BATH(S) STYLE	<u>2</u>	PHYS. % GOOD	<u>9</u> %
4. ASB/ASP 9. Other		1. Good 3. Old Style		FUNCT. % GOOD	<u>9</u> %
5. T1-11		2. Typical 4. Obsolete		FUNCT. CODE	
ROOF SURFACE	<u>1</u>	# ROOMS	<u>3</u>	1. Incomp. 5. CDU	
1. Asphalt 4. Comp.		# BEDROOMS	<u>1</u>	2. Overbuilt 6. Style	
2. Slate 5. Wood		# FULL BATHS	<u>1</u>	3. Delap. 7. Layout	
3. Metal 6. Other		# HALF BATHS	<u>1</u>	4. Small Size 8. Other	
S/F MASONRY TRIM	<u>1974</u>	# ADDN FIXTURES	<u>1</u>	9. None	
YEAR BUILT		# FIREPLACES	<u>1</u>	ECON. % GOOD	<u>9</u> %
YEAR REMODELED		# HEARTHES	<u>1</u>	ECON. CODE	<u>5</u>
FOUNDATION		LAYOUT		1. Location 3. Services	
1. Conc. 4. Wood		1. Typical 2. In adeq.	<u>9</u>	2. Encroach 9. None	
2. C Blk 5. Stab		ATTIC		ENTRANCE CODE	<u>5</u>
3. Br./Stone 6. Piers		1. 1/4 Fin 4. Full Fin.		1. Inspct. 3. Vacant	
BASEMENT	<u>4</u>	2. 1/2 Fin. 5. FV/Stairs		2. Refused 5. Estim.	
1. 1/4 3. 3/4 5. Crawl		3. 3/4 Fin. 9. None		3. Info Only	
2. 1/2 4. Full 6. None		INT COMP TO EXIT + - -		INFO. CODE	<u>5</u>
BSMT GAR # CARS	<u>0</u>	INSPECTED BY	<u>RAK</u>	1. Owner 4. Agent	
WET BASEMENT	<u>1</u>	DATE INSPECTED	<u>9-30-05</u>	2. Relative 5. Estimate	
1. Dry 3. Wet				3. Tenant 6. Other	
2. Damp 9. None				2. Refused 5. Estim.	



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
<u>15</u>	<u>001</u>	<u>1974</u>	<u>1008</u>					1. 1S Fr.
<u>OFF</u>	<u>021</u>		<u>0224</u>					2. 2S Fr.
<u>Bay</u>	<u>025</u>		<u>0016</u>					3. 3S Fr.
<u>Shed</u>	<u>024</u>		<u>0048</u>					4. 1 1/2S Fr.
<u>Shed</u>	<u>024</u>		<u>0120</u>					5. 1 3/4S Fr.
<u>EFP</u>	<u>022</u>		<u>0030</u>					6. 2 1/2S Fr.
<u>GAR</u>	<u>023</u>		<u>0765</u>	<u>3</u>				Add 10 for Bsmt
<u>Hot tub</u>	<u>069</u>		<u>1</u>					21. OFP
<u>DK</u>	<u>065</u>		<u>0120</u>					22. EFP
								23. Garage
								24. Shed
								25. Bay Window
								26. Overhang
								27. Unf. Bsmt
								28. Unf. Attic
								29. Fin. Attic
								Add 20 for 2 Story
								61. Carport
								62. Patio
								63. Swimming Pool
								64. Tennis Court
								65. Stable w/loft
								66. Greenhouse
								67. Natatorium
								68. Wood Deck
								69. Jacuzzi

PHOTO

NOTES: