



MAP 52 LOT 3


ACCOUNT NO. *est*

BUILDING RECORD

ADDRESS

1426 CARD NO. OF

|   |      |   |  |   |
|---|------|---|--|---|
| <b>BUILDING STYLE</b><br>1. Conv. 8. Split Lev.<br>2. Ranch 7. Contemp.<br>3. R. Ranch 8. Log<br>4. Cape 9. Other<br>5. Garrison      | 3    | <b>S/F BSMT LIVING</b><br>400   | <b>INSULATION</b><br>1. Full 4. Minimal<br>2. Heavy 9. None<br>3. Capped   | 1 |
| <b>DWELLING UNITS</b>   |      | <b>FIN BSMT GRADE</b><br>3<br>100   | <b>UNFINISHED %</b><br>%   |   |
| <b>OTHER UNITS</b>  | 1    | <b>HEAT TYPE</b><br>1. HW BB 6. Grav. WA<br>2. HW CI 7. Electric<br>3. HW Radiant 8. Units<br>4. Steam 9. No Heat<br>5. FWA | <b>GRADE &amp; FACTOR</b><br>1. E 4. B<br>2. D 5. A<br>3. C 6. AA  | 3 |
| <b>STORIES</b><br>1. One 4. 1 1/2<br>2. Two 5. 1 3/4<br>3. Three 6. 2 1/2   |      | <b>COOL TYPE</b><br>1. Central 9. None  | <b>SQ. FOOTAGE</b><br>818  |   |
| <b>EXTERIOR WALLS</b><br>1. Clapboard 6. BR./Stone<br>2. WD.SH. 7. Novelty<br>3. Comp. 8. AL/Vinyl<br>4. ASB/ASP 9. Other<br>5. T1-11 | 1    | <b>KITCHEN STYLE</b><br>1. Good 3. Old Style<br>2. Typical 4. Obsolete  | <b>CONDITION</b><br>1. Poor 5. Avg +<br>2. Fair 6. Good<br>3. Avg - 7. V Good<br>4. Avg. 8. Exc.   | 4 |
| <b>ROOF SURFACE</b><br>1. Asphalt 4. Comp.<br>2. Slate 5. Wood<br>3. Metal 6. Other   |      | <b>BATH(S) STYLE</b><br>1. Good 3. Old Style<br>2. Typical 4. Obsolete  | <b>PHYS. % GOOD</b><br>%   |   |
| <b>S/F MASONRY TRIM</b>   | 1975 | <b># ROOMS</b><br>7   | <b>FUNCT. % GOOD</b><br>%  | 9 |
| <b>YEAR BUILT</b>   |      | <b># BEDROOMS</b><br>7  | <b>FUNCT. CODE</b><br>1. Incomp. 5. CDU<br>2. Overbuilt 6. Style<br>3. Delap. 7. Layout<br>4. Small Size 8. Other<br>9. None   |   |
| <b>YEAR REMODELED</b>   | 1    | <b># FULL BATHS</b><br>1  | <b>ECON. % GOOD</b><br>%   | 9 |
| <b>FOUNDATION</b><br>1. Conc. 4. Wood<br>2. C Blk 5. Slab<br>3. Br./Stone 6. Piers  |      | <b># HALF BATHS</b><br>1  | <b>ECON. CODE</b><br>1. Location 3. Services<br>2. Encroach 9. None  |   |
| <b>BASEMENT</b><br>1. 1/4 3. 3/4 5. Crawl<br>2. 1/2 4. Full 6. None   | 4    | <b># ADDN FIXTURES</b><br>9   | <b>ENTRANCE CODE</b><br>1. Inspt. 3. Vacant<br>2. Refused 5. Estim.<br>3. Info Only  | 5 |
| <b>BSMT GAR # CARS</b><br>1. Dry 3. Wet<br>2. Damp 9. None  |      | <b>INT COMP TO EXIT + = -</b>   | <b>INFO. CODE</b><br>1. Owner 4. Agent<br>2. Relative 5. Estimate<br>3. Tenant 6. Other<br>2. Refused 5. Estim.  |   |
| <b>WET BASEMENT</b>   | 1    | <b>INSPECTED BY</b><br>RAK  | <b>CODES</b><br>1. 1S Fr.<br>2. 2S Fr.<br>3. 3S Fr.<br>4. 1 1/2S Fr.<br>5. 1 3/4S Fr.<br>6. 2 1/2S Fr.<br>Add 10 for Bsmt<br>21. OFP<br>22. EFP<br>23. Garage<br>24. Shed<br>25. Bay Window<br>26. Overhang<br>27. Unf. Bsmt<br>28. Unf. Attic<br>29. Fin. Attic<br>Add 20 for 2 Story<br>61. Carport<br>62. Patio<br>63. Swimming Pool<br>64. Tennis Court<br>65. Stable w/loft<br>66. Greenhouse<br>67. Natorium<br>68. Wood Deck<br>69. Jacuzzi | 5 |
| <b>DATE INSPECTED</b><br>10-7-05  |      | <b>ADDITIONS, OUTBUILDINGS &amp; IMPROVEMENTS</b>   |  |   |



|      | TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD |        |
|------|------|------|-------|-------|------|--------------|--------|
|      |      |      |       |       |      | Phys.        | Funct. |
| 15   | 001  | 1975 | 0818  | ---   | ---  | ---          | ---    |
| 15   | 001  | ---  | 144   | ---   | ---  | ---          | ---    |
| ofp  | 021  | ---  | 48    | ---   | ---  | ---          | ---    |
| OH   | 026  | ---  | 30    | ---   | ---  | ---          | ---    |
| OGAR | 023  | 1998 | 364   | ---   | ---  | ---          | ---    |

NOTES:

PHOTO