




MAP 52 LOT 17 ACCOUNT NO. 927 BUILDING RECORD ADDRESS CARD NO. OF

BUILDING STYLE		S/F BSMT LIVING		INSULATION		PERCENT GOOD		CODES
1. Conv.	6. Split Lev.	FIN BSMT GRADE	1. Full	1. Full	Phys.	Funct.		
2. Ranch	7. Contemp.		2. Heavy	2. Poor	%	%	1. 1S Fr.	
3. R. Ranch	8. Log		3. Capped	3. Avg	%	%	2. 2S Fr.	
4. Cape	9. Other		4. None	4. Avg +	%	%	3. 3S Fr.	
DWELLING UNITS		HEAT TYPE		UNFINISHED %		GRADE & FACTOR		4. 1 1/2S Fr.
5. Garrison	1. HW BB	1. HW BB	5. None	3. Capped	%	%	5. 1 3/4S Fr.	
OTHER UNITS		KITCHEN STYLE		ECON. % GOOD		ENTRANCE CODE		6. 2 1/2S Fr.
OTHER STORIES	2. Two	1. Good	1. Full	1. E	%	%	1. Incomp.	
1. One	5. 1 3/4	2. Typical	2. Heavy	2. D	%	%	2. Overbuilt	
2. Two	8. 2 1/2	3. Old Style	3. Capped	3. C	%	%	3. Delap.	
3. Three		4. Obsolete	4. None	4. AA	%	%	4. Small Size	
EXTERIOR WALLS		BATH(S) STYLE		PHYS. % GOOD		FUNCT. CODE		5. CDU
1. Cleaport	6. Br/Stone	1. Good	1. Full	1. Poor	%	%	6. Style	
2. WD. SH	7. Novelty	2. Typical	2. Heavy	2. Fair	%	%	7. Layout	
3. Comp.	8. AL/Almly	3. Old Style	3. Capped	3. Avg	%	%	8. Other	
4. ASB/ASP	9. Other	4. Obsolete	4. None	4. Avg +	%	%	9. None	
5. T1-11		5. None	5. Minimal	5. Avg +	%	%		
ROOF SURFACE		# BEDROOMS		CON. CODE		ECON. CODE		
1. Asphalt	4. Comp.	1. Typical	2. Overbuilt	1. Poor	%	%	1. Location	
2. Slate	5. Wood	2. In ateq.	3. Delap.	2. Fair	%	%	2. Entrance	
3. Metal	6. Other	3. Full Fin.	4. Small Size	3. Avg	%	%	3. Services	
S/F MASONRY TRIM		# FULL BATHS		UNFINISHED %		ENTRANCE CODE		
1. Full	1. Full	1. 1/4 Fin.	1. Full	3. Capped	%	%	1. Incomp.	
2. 1/2	2. 1/2	2. 1/2 Fin.	2. Heavy	4. AA	%	%	2. Overbuilt	
3. 3/4	3. 3/4	3. 3/4 Fin.	3. Capped	5. A	%	%	3. Delap.	
4. Full	4. Full	4. Full Fin.	4. None	6. AA	%	%	4. Small Size	
YEAR BUILT		# ADDN FIXTURES		PHYS. % GOOD		FUNCT. CODE		
YEAR REMODELED	# HEARTHS	# ROOMS	# BEDROOMS	1. Poor	%	%	1. Location	
FOUNDATION	LAYOUT	# FULL BATHS	# HALF BATHS	2. Fair	%	%	2. Entrance	
1. Conc.	1. Typical	1. 1/4 Fin.	1. Full Fin.	3. Avg	%	%	3. Services	
2. C Bk	2. In ateq.	2. 1/2 Fin.	2. Full Fin.	4. Avg +	%	%	4. None	
3. Br/Stone	3. Full Fin.	3. 3/4 Fin.	3. Full Fin.	5. A	%	%	5. Vacant	
BASEMENT	4. Full Fin.	4. Full Fin.	4. Full Fin.	6. AA	%	%	6. Estim.	
1. 1/4	5. None	5. None	5. None	7. V Good	%	%	7. Into Only	
2. 1/2	6. None	6. None	6. None	8. Exc.	%	%	8. Info Only	
3. 3/4	7. None	7. None	7. None	9. None	%	%	9. Agent	
4. Full	8. None	8. None	8. None		%	%	10. Estimate	
BSMT GAR # CARS	9. None	9. None	9. None		%	%	11. Tenant	
1. Dry	1. None	1. None	1. None		%	%	12. Refused	
2. Damp	2. None	2. None	2. None		%	%	13. Refused	
WET BASEMENT		DATE INSPECTED		INFO. CODE				
1. Wet	3. Wet			1. Owner	4. Agent			
2. Dry	4. Dry			2. Relative	5. Estimate			
3. None	5. None			3. Tenant	6. Other			
4. None	6. None			4. Refused	7. Estim.			
ADDITIONS, OUTBUILDINGS & IMPROVEMENTS		DATE INSPECTED		INFO. CODE				
				1. Owner	4. Agent			
				2. Relative	5. Estimate			
				3. Tenant	6. Other			
				4. Refused	7. Estim.			



PHOTO

NOTES:

15  
DK  
OH  
Sld  
1979  
864  
100  
30  
01/94

69. Jaruzzi