


BUILDING RECORD

MAP 52 LOT 23 ACCOUNT NO. ADDRESS CARD NO. OF

| | | | | | | | |
|---------------------------|---|-------------------------------|------------------------|---------------------------|--------------------|-----------------------|---------|
| BUILDING STYLE | | S/F BSMT LIVING | 600 | INSULATION | | | |
| 1. Conv. 6. Split Lev. | 3 | FIN BSMT GRADE | 3 | 1. Full 4. Minimal | 1 | | |
| 2. Ranch 7. Contemp. | | | 100 | 2. Heavy 9. None | | | |
| 3. R. Ranch 8. Log | | | | 3. Capped | | | |
| 4. Cape 9. Other | | | | UNFINISHED % | | % | |
| 5. Garrison | | | | GRADE & FACTOR | | | |
| DWELLING UNITS | | HEAT TYPE | | 1. E 4. B | 3 | | |
| OTHER UNITS | | 1. HW BB 6. Grav. WA | 1 | 2. D 5. A | | | |
| STORIES | 1 | 2. HW CI 7. Electric | | | | 3. C 6. AA | |
| 1. One 4. 1 1/2 | | 3. HW Radiant 8. Units | | | | SQ. FOOTAGE | 818 |
| 2. Two 5. 1 3/4 | | 4. Steam 9. No Heat | | | | CONDITION | 7 |
| 3. Three 6. 2 1/2 | | 5. FWA | | % | 1. Poor 5. Avg + | | |
| EXTERIOR WALLS | | COOL TYPE | | 2. Fair 6. Good | 9 | | |
| 1. Clapboard 6. BR./Stone | 1 | 1. Central 9. None | 9 | 3. Avg - 7. V Good | | | |
| 2. WD.SH. 7. Novelty | | | 2 | 4. Avg. 8. Exc. | | | |
| 3. Comp. 8. AL/Vinyl | | | | PHYS. % GOOD | | % | |
| 4. ASB/ASP 9. Other | | | | 2 | | FUNCT. % GOOD | % |
| 5. T1-11 | | | | | FUNCT. CODE | | |
| ROOF SURFACE | | KITCHEN STYLE | | 1. Incomp. 5. CDU | 9 | | |
| 1. Asphalt 4. Comp. | 1 | 1. Good 3. Old Style | 2 | 2. Overbuilt 6. Style | | | |
| 2. Slate 5. Wood | | | | 3. Delap. 7. Layout | | | |
| 3. Metal 6. Other | | | | 4. Small Size 8. Other | | | |
| S/F MASONRY TRIM | | | | BATH(S) STYLE | | | 9. None |
| 1. Conc. 4. Wood | | | | 1. Good 3. Old Style | 2 | ECON. % GOOD | % |
| 2. C Blk 5. Stab | | 2. Typical 4. Obsolete | | ECON. CODE | 9 | | |
| 3. Br./Stone 6. Piers | | # ROOMS | 3 | 1. Location 3. Services | 1 | | |
| BASEMENT | | # BEDROOMS | 2 | 2. Encroach 9. None | | | |
| 1. 1/4 3. 3/4 5. Crawl | 4 | # FULL BATHS | 2 | ENTRANCE CODE | | | |
| 2. 1/2 4. Full 6. None | | | # HALF BATHS | | | 1. Inspect. 3. Vacant | |
| BSMT GAR # CARS | | 0 | # ADDN FIXTURES | | | 2. Refused 5. Estim. | |
| WET BASEMENT | | 1 | # FIREPLACES | 1 | 3. Info Only | | |
| 1. Dry 3. Wet | | | # HEARTHES | 1 | INFO. CODE | 1 | |
| 2. Damp 9. None | | LAYOUT | | 1. Owner 4. Agent | 1 | | |
| | | 1. Typical 2. In adeg. | 1 | 2. Relative 5. Estimate | | | |
| | | ATTIC | | 3. Tenant 6. Other | | | |
| | | 1. 1/4 Fin 4. Full Fin. | 9 | 2. Refused 5. Estim. | | | |
| | | 2. 1/2 Fin. 5. Fl/Stairs | | | | | |
| | | 3. 3/4 Fin. 9. None | | | | | |
| | | INT COMP TO EXIT + = - | | | | | |
| | | INSPECTED BY | RAK | | | | |
| | | DATE INSPECTED | 10/20/05 | | | | |



ADDITIONS, OUTBUILDINGS & IMPROVEMENTS

| | TYPE | YEAR | UNITS | GRADE | COND | PERCENT GOOD | | CODES |
|-------|------|------|-------|-------|------|--------------|--------|--------------------|
| | | | | | | Phys. | Funct. | |
| 13 | 001 | | 818 | | | % | % | 1. 1S Fr. |
| 04 | 026 | | 30 | | | % | % | 2. 2S Fr. |
| DK | 068 | | 170 | | | % | % | 3. 3S Fr. |
| A/Gar | 047 | | 672 | | | % | % | 4. 1 1/2S Fr. |
| Shed | 024 | | 80 | | | % | % | 5. 1 3/4S Fr. |
| OP | 021 | | 36 | | | % | % | 6. 2 1/2S Fr. |
| | | | | | | % | % | Add 10 for Bsmt |
| | | | | | | % | % | 21. OFP |
| | | | | | | % | % | 22. EFP |
| | | | | | | % | % | 23. Garage |
| | | | | | | % | % | 24. Shed |
| | | | | | | % | % | 25. Bay Window |
| | | | | | | % | % | 26. Overhang |
| | | | | | | % | % | 27. Unf. Bsmt |
| | | | | | | % | % | 28. Unf. Attic |
| | | | | | | % | % | 29. Fin. Attic |
| | | | | | | % | % | Add 20 for 2 Story |
| | | | | | | % | % | 61. Carport |
| | | | | | | % | % | 62. Patio |
| | | | | | | % | % | 63. Swimming Pool |
| | | | | | | % | % | 64. Tennis Court |
| | | | | | | % | % | 65. Stable w/loft |
| | | | | | | % | % | 66. Greenhouse |
| | | | | | | % | % | 67. Natatorium |
| | | | | | | % | % | 68. Wood Deck |
| | | | | | | % | % | 69. Jacuzzi |

PHOTO

NOTES: