




BUILDING RECORD

MAP 55 LOT 10 ACCOUNT NO. ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>	
1. Conv. 6. Split Lev.	MH	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal	
2. Ranch 7. Contemp.				2. Heavy 9. None	
3. R. Ranch 8. Log				3. Capped	
4. Cape 9. Other				<b>UNFINISHED %</b>	%
5. Garrison				<b>GRADE &amp; FACTOR</b>	
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>	5	1. E 4. B	3
<b>OTHER UNITS</b>		1. HW BB 6. Grav. WA		2. D 5. A	672
<b>STORIES</b>	1	2. HW CI 7. Electric		3. C 6. AA	
1. One 4. 1 1/2		3. HW Radiant 8. Units	9 %	<b>SQ. FOOTAGE</b>	
2. Two 5. 1 3/4		4. Steam 9. No Heat		<b>CONDITION</b>	
3. Three 6. 2 1/2		<b>COOL TYPE</b>		1. Poor 5. Avg +	5
<b>EXTERIOR WALLS</b>		1. Central 9. None	2	2. Fair 6. Good	
1. Clapboard 6. BR./Stone	1	<b>KITCHEN STYLE</b>		3. Avg - 7. V Good	
2. WD.SH. 7. Novelty		1. Good 3. Old Style	2	4. Avg. 8. Exc. %	
3. Comp. 8. AL/Vinyl		2. Typical 4. Obsolete		<b>PHYS. % GOOD</b>	%
4. ASB/ASP 9. Other		<b>BATH(S) STYLE</b>	2	<b>FUNCT. % GOOD</b>	%
5. T1-11		1. Good 3. Old Style		<b>FUNCT. CODE</b>	
<b>ROOF SURFACE</b>	1	2. Typical 4. Obsolete		1. Incomp. 5. CDU	9
1. Asphalt 4. Comp.		<b># ROOMS</b>	2	2. Overbuilt 6. Style	
2. Slate 5. Wood		<b># BEDROOMS</b>		3. Delap. 7. Layout	
3. Metal 6. Other		<b># FULL BATHS</b>		4. Small Size 8. Other	
<b>S/F MASONRY TRIM</b>		<b># HALF BATHS</b>		9. None	
<b>YEAR BUILT</b>	1925	<b># ADDN FIXTURES</b>		<b>ECON. % GOOD</b>	%
<b>YEAR REMODELED</b>	2012	<b># FIREPLACES</b>		<b>ECON. CODE</b>	9
<b>FOUNDATION</b>		<b># HEARTHES</b>	1	1. Location 3. Services	
1. Conc. 4. Wood		<b>LAYOUT</b>		2. Encroach 9. None	
2. C Blk 5. Slab		1. Typical 2. In adeq.		<b>ENTRANCE CODE</b>	5
3. Br./Stone 6. Piers		<b>ATTIC</b>	9	1. Inspct. 3. Vacant	
<b>BASEMENT</b>	6	1. 1/4 Fin. 4. Full Fin.		2. Refused 5. Estim.	
1. 1/4 3. 3/4 5. Crawl		2. 1/2 Fin. 5. Fl/Stairs		3. Info Only	
2. 1/2 4. Full 6. None		3. 3/4 Fin. 9. None		<b>INFO. CODE</b>	5
<b>BSMT GAR # CARS</b>		<b>INT COMP TO EXIT + - -</b>		1. Owner 4. Agent	
<b>WET BASEMENT</b>	9	<b>INSPECTED BY</b>	RAK	2. Relative 5. Estimate	
1. Dry 3. Wet		<b>DATE INSPECTED</b>	10-28-05	3. Tenant 6. Other	
2. Damp 9. None				2. Refused 5. Estim.	



1925

Remodeled

PHOTO

ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						PERCENT GOOD		CODES
TYPE	YEAR	UNITS	GRADE	COND	Phys.	Funct.		
MH	997	1925	672	3.00	6	%	%	1. 1S Fr.
DK	68		168			%	%	2. 2S Fr.
			672			%	%	3. 3S Fr.
						%	%	4. 1 1/2S Fr.
						%	%	5. 1 3/4S Fr.
						%	%	6. 2 1/2S Fr.
						%	%	Add 10 for Bsmt
						%	%	21. OFP
						%	%	22. EFP
						%	%	23. Garage
						%	%	24. Shed
						%	%	25. Bay Window
						%	%	26. Overhang
						%	%	27. Unf. Bsmt
						%	%	28. Unf. Attic
						%	%	29. Fin. Attic
						%	%	Add 20 for 2 Story
						%	%	61. Carport
						%	%	62. Patio
						%	%	63. Swimming Pool
						%	%	64. Tennis Court
						%	%	65. Stable w/loft
						%	%	66. Greenhouse
						%	%	67. Natatorium
						%	%	68. Wood Deck
						%	%	69. Jacuzzi

NOTES:

① shed 24 64  
② shed 24 80