




MAP **55** LOT **45** ACCOUNT NO. ADDRESS CARD NO. OF

<b>BUILDING STYLE</b>		<b>S/F BSMT LIVING</b>		<b>INSULATION</b>		
1. Conv. 8. Split Lev.	MH	<b>FIN BSMT GRADE</b>		1. Full 4. Minimal		
2. Ranch 7. Contemp.				2. Heavy 9. None		
3. R. Ranch 6. Log				3. Capped		
4. Cape 9. Other				<b>UNFINISHED %</b>	%	
5. Garrison				<b>GRADE &amp; FACTOR</b>		
<b>DWELLING UNITS</b>		<b>HEAT TYPE</b>	5	1. E 4. B	3	
<b>OTHER UNITS</b>		1. HW BB 6. Grav. WA		2. D 5. A		
<b>STORIES</b>	1	2. HW CI 7. Electric		3. C 6. AA	924	
1. One 4. 1 1/2		3. HW Radiant 8. Units		<b>SQ. FOOTAGE</b>	924	
2. Two 5. 1 3/4		4. Steam 9. No Heat		<b>CONDITION</b>	3	
3. Three 6. 2 1/2		5. FWA	9 %	1. Poor 5. Avg +		
<b>EXTERIOR WALLS</b>		<b>COOL TYPE</b>		2. Fair 6. Good		
1. Clapboard 6. BR./Stone	T	1. Central 9. None	9 %	3. Avg - 7. V Good		
2. WD.SH. 7. Novelty				4. Avg. 8. Exc.	%	
3. Comp. 8. AL/Vinyl				<b>PHYS. % GOOD</b>	%	
4. ASB/ASP 9. Other				<b>FUNCT. % GOOD</b>	%	
5. T1-11				<b>FUNCT. CODE</b>		
<b>ROOF SURFACE</b>		<b>KITCHEN STYLE</b>		1. Incomp. 5. CDU	9	
1. Asphalt 4. Comp.	1	1. Good 3. Old Style	2	2. Overbuilt 6. Style		
2. Slate 5. Wood				3. Delap. 7. Layout		
3. Metal 6. Other				4. Small Size 8. Other		
<b>S/F MASONRY TRIM</b>			<b>BATH(S) STYLE</b>	2	9. None	
<b>YEAR BUILT</b>		1990?	1. Good 3. Old Style		<b>ECON. % GOOD</b>	%
<b>YEAR REMODELED</b>		2. Typical 4. Obsolete		<b>ECON. CODE</b>	9	
<b>FOUNDATION</b>		<b># ROOMS</b>	2	1. Location 3. Services		
1. Conc. 4. Wood		<b># BEDROOMS</b>	2	2. Encroach 9. None		
2. C Blk 5. Stab		<b># FULL BATHS</b>	2	<b>ENTRANCE CODE</b>		
3. Br./Stone 6. Piers		<b># HALF BATHS</b>		1. Inspt. 3. Vacant	5	
<b>BASEMENT</b>		<b># ADDN FIXTURES</b>		2. Refused 5. Estim.		
1. 1/4 3. 3/4 5. Crawl	6	<b># FIREPLACES</b>		3. Info Only		
2. 1/2 4. Full 6. None			<b># HEARTHES</b>		<b>INFO. CODE</b>	5
<b>BSMT GAR # CARS</b>			<b>LAYOUT</b>	1	1. Owner 4. Agent	
<b>WET BASEMENT</b>			1. Typical 2. In adeg.	9	2. Relative 5. Estimate	
1. Dry 3. Wet		9	<b>ATTIC</b>		3. Tenant 6. Other	
2. Damp 9. None		1. 1/4 Fin 4. Full Fin.		2. Refused 5. Estim.		
		2. 1/2 Fin. 5. Fl/Stairs				
		3. 3/4 Fin. 9. None				
		<b>INT COMP TO EXIT + = -</b>				
		<b>INSPECTED BY</b>	RAK			
		<b>DATE INSPECTED</b>	11-11-05			



DOG!  
1990's

**ADDITIONS, OUTBUILDINGS & IMPROVEMENTS**

	TYPE	YEAR	UNITS	GRADE	COND	PERCENT GOOD	
						Phys.	Funct.
MH	998	1990?	924			%	%
OK	68		192			%	%
55	223					%	%
						%	%
						%	%
						%	%
						%	%
						%	%
						%	%
① Shed	24		130	3	3	%	%

- CODES**
- 1. 1S Fr.
  - 2. 2S Fr.
  - 3. 3S Fr.
  - 4. 1 1/2S Fr.
  - 5. 1 3/4S Fr.
  - 6. 2 1/2S Fr.
  - Add 10 for Bsmt
  - 21. OFP
  - 22. EFP
  - 23. Garage
  - 24. Shed
  - 25. Bay Window
  - 26. Overhang
  - 27. Unf. Bsmt
  - 28. Unf. Attic
  - 29. Fin. Attic
  - Add 20 for 2 Story
  - 61. Carport
  - 62. Patio
  - 63. Swimming Pool
  - 64. Tennis Court
  - 65. Stable w/loft
  - 66. Greenhouse
  - 67. Natatorium
  - 68. Wood Deck
  - 69. Jacuzzi

PHOTO

NOTES: